ZUMBRO RWER

ZUMBRO LAKE DAM Wabasha County, Minnesola Inventory no 358

INSPECTION REPORT



Prepared by

DEPARTMENT OF THE ARMY ST. PAUL DISTRICT, CORPS OF ENGINEERS ST. PAUL, MINNESOTA

STATE of MINNESOTA

For

SEPTEMBER 1979

# TABLE OF CONTENTS

General Summary

Section 1 Project Information and Typical Drawings					
Section 2	Background Engineering Data				
Section 3	Hydraulics and Hydrologic Evaluation				
Section 4	Evaluation of the Physical Aspects of Operation and Maintenance				
Section 5	Geotechnical Evaluation				
Section 6	Structural Evaluation				
Appendix A	Field Inspection Report				
Appendix B	Hydrology and Hydraulics Study Checklist				

Appendix C

Photographs

#### GENERAL SUMMARY

The procedures and methodolgy used for the design of dams has undergone major evolution within the last half a century. Because the majority of dams within the State were constructed during or prior to this evolution, often there is little available design data which conforms to current practice. The emphasis of the National Dams Inspection Program is not to develop the data for a comprehensive analysis of a structure, but rather to identify conditions which constitute an existing or potential hazard. By necessity, the identification process presented in this report is generally limited to conditions which may be identified through the field inspection, approximate computations and other readily available sources of information. The contents of this report should not be treated as an in-depth engineering evaluation.

The Zumbro Lake Dam and powerhouse was constructed in 1919 for purposes of hydroelectric power generation. The dam was constructed for the City of Rochester, which still owns and maintains the dam. The dam currently generates electric power used by the City of Rochester and is operated by the City of Rochester Electric Department. The dam remains essentially unchanged from its original configuration, however, repair work has been accomplished on the existing structure since its construction. The dam consists mainly of a mass concrete gravity cross-section which serves as an uncontrolled overflow spillway. Other components are a powerhouse and non-overflow sections at the abutments. The maximum hydraulic height of the dam is approximately 80 feet and the total length of the dam is 900 feet.

The Zumbro Lake Dam is not located within an urban area, however, there are several residences downstream of the dam and the potential for additional development is high. There is also a campground immediately downstream of the dam which is used during the summer months. A sudden failure of the Zumbro Lake Dam would result in loss of life downstream and damage to downstream residences. Failure of the Zumbro Lake Dam due to either normal pool conditions or flood flow conditions would both result in loss of life downstream of the dam. Based on the potential for loss of life and damage to the areas downstream, the Zumbro Lake Dam is categorized as a "high hazard" dam.

#### CONCLUSIONS AND RECOMMENDATIONS

Evaluation of the dam included an on-site inspection, a review of available data, and an evaluation of the hydraulic and hydrologic characteristics of the dam and reservoir. In addition, an evaluation of the operation and maintenance, geotechnical and structural aspects was conducted. The following are the major conclusions and recommendations resulting from the evaluation:

### 1. Discharge Capacity

- The Zumbro Lake Dam does not meet accepted dam safety criteria a. because it is not capable of passing the spillway design flood as recommended by the dam safety guidelines. The spillway design flood, as recommended by the dam safety guidelines, is the Probable Maximum Flood or 290,000 cfs. It is estimate that the overtopping discharge is approximately 50,000 cfs corresponding to the flood with 0.35 percent probability of annual occur-The 100-year flood or the flood with a 1 percent probarence. bility of annual occurrence has a discharge of 37,500 cfs which can be passed without overtopping the dam. Failure of the Zumbro Lake Dam resulting from overtopping would probably significantly increase the hazard to loss of life downstream from the dam from that which would exist just before overtopping failure because the tailwater elevations along the downstream dwellings would be at or near the foundations of the dwellings which would not cause them to be evacuated. Therefore, failure of the Zumbro Lake Dam due to overtopping would result in a high probability for loss of life downstream of the dam. Therefore:
  - 1. It is recommended that a spillway design flood be determined on a basis of more detailed evaluations of the hydrologic and hydraulic conditions and downstream damage potential and that the modifications required to allow safe passage of the spillway design flood be implemented.

- <u>It is recommended</u> that a documented flood warning plan be developed for closing nearby bridges, evacuating nearby residences, and evacuating the downstream camping grounds during major floods.
- 3. It is recommended that a detailed floodplain analysis be made downstream of the dam to determine the hazards to the camping grounds and local residences.
- 4. <u>It is recommended</u> that a documented hydraulic operation plan be developed and implemented for the spillway especially as it relates to the flood warning plan.

## 2. Operation Plan

a. The Zumbro Lake Dam currently primarily functions as an uncontrolled spillway, although there is flow passed through the turbines which is controlled by the City of Rochester Electric Department. The only other operable outlets for the dam are a small ice chute gate adjacent to the powerhouse at the crest of the dam and a small diversion tunnel located at the center of the spillway near the base of the dam. The discharge capacities of these outlets are small. Operation of discharge facilities other than the turbines has been very infrequent.

#### 3. Inspection and Maintenance Programs

- a. No systematic program of periodic inspection has been developed for the Zumbro Lake Dam. A continuing program of inspection is a necessary part of an effective maintenance program. Therefore:
  - 1. It is recommended that a documented program of inspection and maintenance be developed and implemented. This inspection program should be designed to detect deficiences related to the seepage, scour and structural distress.

#### 4. Foundation Evaluation

a. The Zumbro Lake Dam is constructed upon a sandstone bedrock which is light brown in color and well cemented. The dam is keyed into the bedrock along the valley walls. The dam foundation would probably meet current recommended design criteria in regards to foundation stability.

### 5. Seepage and Scour

The dam has a past history of seepage through the spillway concrete construction joints. Repairs were conducted during 1935 and 1961 to repair this situation. Therefore:

- 1. It is recommended that, during periods of low flow when the spillway surface is dry, that an inspection be made to determine the extent of seepage through the spillway.
- b. Both abutments have a considerable amount of tree growth. However, it is not recommended that these trees be removed upstream of the concrete core wall because the massive concrete core walls and mass concrete non-overflow sections of the dam would not be adversely affected by tree growth. There is also some severe erosion occurring on the upstream bank near the left abutment. Therefore:
  - 1. It is recommended that the banks upstream of the left abutment be stabilized and the trees removed from the riprap on the banks upstream of the right abutment.
- c. A scour hole in the downstream bedrock channel was detected. Therefore:
  - It is recommended that the scour holes should be periodically sounded to ensure that unchecked scour does not lead to possible stability problems.

#### 6. Structural Evaluation

The Zumbro Lake Dam would probably meet current recommended design criteria in regards to overturning stability. However, the dam probably does not meet current recommended design criteria in regards to sliding stability, however, its stability in regards to sliding is probably satisfactory. The structural strength of the Zumbro Lake Dam structural components may meet current recommended design criteria. Temperature cracking was observed on the interior of the powerhouse. Severe deterioration of the right half of the spillway surface was observed. However, this does not present a hazard to the structural stability of the dam but may lead to accelerated concrete deterioration or hydraulic inefficiency. Therefore:

- 1. <u>It is recommended</u> that the severe spillway surface deterioration be repaired in the near future to reduce the amount of work and materials required and to improve the hydraulic operation of the spillway.
- 2. It is recommended that additional study be accomplished to conclusively evaluate the stability of the Zumbro Lake Dam.
- 3. <u>It is recommended</u> that the cracks in the powerhouse superstructure be repaired to prevent possible accelerated concrete deterioration.

### 7. Interim Measures

- A high probability for loss of life downstream of the dam exists during large floods and is a result of sudden failure of the Zumbro Lake Dam during most flow conditions. Therefore:
  - 1. It is recommended that the residents downstream of the dam be informed of the hazard associated with the dam and that a flood warning and evacuation plan be developed and implemented during flood conditions.

### 8. Hazard Classification for Assessment

a. This report verifies that the dam is properly classified as a high hazard dam because of the proximity of the downstream residences and public use facilities. However, if the measures recommended in this report are implemented, there would be a "low threat" of failure of the Zumbro Lake Dam.

SIGNATURES OF INSPECTION TEAM

TEAM LEADER

Vangl E. Zuelke harles C. Rehn

BARR ENGINEERING/CO. Minneapolis, Minnesota

# INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM ZUMBRO LAKE DAM INVENTORY NO. 358 SOUTH FORK ZUMBRO RIVER, MINNESOTA

# SECTION I PROJECT INFORMATION

# 1.1 GENERAL

### a. Authority

1) The F.Y. 1978 Public Works Appropriation Act, Public Law 95-96.

2) The National Dam Safety Act, Public Law 92-367, 8 August 1972.

# b. Purpose of Inspection

The purpose of the inspection is to identify the existence of conditions which could threaten the integrity of the structure and thereby creating a downstream hazard.

# 1.2 DESCRIPTION OF PROJECT

# a. Description of Dam and Appurtenances

The principal components of the Zumbro Lake Dam consists of a 243.5 foot long right non-overflow section, 440 foot long uncontrolled mass concrete spillway, a 100-foot long powerhouse, and a 117-foot long left non-overflow

<sup>\*</sup>Left and right are defined facing downstream.

Note: N/A means NOT APPLICABLE N/O means NOT OBSERVED Not Available means NOT AVAILABLE

section as shown on Plate 1-2. The spillway, powerhouse and non-overflow sections are presented in more detail in Plates 2-1 through 2-21. The spillway has an uncontrolled crest, a sloping downstream face, a small outlet structure in the center, and an ice chute on the left side of the spillway. The powerhouse is located to the left of the spillway and has two turbine intakes and provisions for a third. The turbine flow is currently remotely controlled from the City of Rochester steam electric generating plant. The right abutment of the non-overflow section is connected to a concrete core cutoff wall and keyed into bedrock.

### b. Location

The Zumbro Lake Dam is located on the Zumbro River 13 miles north of Rochester, Minnesota and approximately 65 miles southeast of Minneapolis-St. Paul. The dam is located in Sec. 27, T109N, R14E.

### c. Size Classification

The maximum storage capacity of the Zumbro Lake Dam is approximately 50,000 acre-feet. The hydraulic height of the dam, as measured from the natural streambed elevation to the top of the dam (in this report determined to be the top of the non-overflow section) is approximately 60 feet. This places the dam in the intermediate size category.

### d. Hazard Classification

High (revised from inventory).

#### e. Ownership

The City of Rochester, Rochester Public Utilities, P.O. Box 6057, Rochester, Minnesota, 55901 is the owner of the Zumbro Lake Dam.

### f. Purpose

The Zumbro Lake Dam is used for generation of hydro-electric power and the reservoir is used for recreational purposes.

#### g. Design and Construction History

The Zumbro Lake Dam was designed by Hugh L. Cooper & Co., Consulting Engineers, of New York. The dam was constructed in 1919 with resurfacing of parts of the spillway conducted in 1935. In 1961, repair work was accomplished on the spillway, which included the addition of a dewatering tunnel through the spillway. Section 2 of this report deals more completely with this subject.

#### h. Normal Operational Procedure

There is no formal documented procedure for operation or maintenance of the Zumbro Lake Dam. However, the City of Rochester Electric Department operates and checks the dam on a regular basis. Reservoir water is used for power generation. The powerhouse is unmanned as the turbines are remotely controlled from the City of Rochester's power plant.

### **1.3 PERTINENT DATA**

Elevations presented are in reference to the datum used on the construction plans for the dam by Hugh L. Cooper Co. (probably 1912 Adj.). The elevations in parenthesis are approximate 1929 Adj. elevations. The 1929 Adj. elevations were derived by using the crest elevation of 915 as noted on the Zumbro Lake, Minnesota U.S.G.S. quadrangle dated 1972. In the following sections of the report, the estimated 1929 Adj. elevation will be used unless noted otherwise.

a. Drainage Area

#### 811 square miles

### b. Discharge at Dam Site (cfs)

Maximum Known Flood at Dam

30,000 (estimated)

Diversion Tunnel at Low Pool Outlet at Pool Elevation 920.0 (915.0)

Diversion Tunnel Outlet at Pool Elevation 930.0 (925.0)

Gated Spillway Capacity at Normal Pool Elevation 950 1060 N/A

	Gated Spillway Capacity at Maximum Pool Elevation	N/A
	Ungated Spillway Capacity at Maximum Pool Elevation	50,000
	Penstock Capacity at Normal Pool Elevation	610
	Penstock Capacity at Maximum Pool Elevation	Not Available
	Total Spillway Capacity at Maximum Pool Elevation	50,000
c.	Elevation (feet above MSL) (1929 Datum)	
	Top of Dam	930.0 <u>+</u> (925.0)
	Maximum Pool Design Surcharge	930.0 <u>+</u> (925.0)
	Flood Control Pool	N/A
	Normal Pool	920.0 (915.0)
	Upstream Portal Invert Diversion Tunnel	978+ (973+)
	Downstream Portal Invert Diversion Tunnel	978+ (973+)
	Stream Bed at Centerline of Dam	
	Maximum Known Tailwater	867 (862)(estimated)
	Top Left Abutment	923.0 (918.0)
	Top Right Abutment	925.0 (920.0)
	Upstream Penstock Invert	898.0 (893.0)
	Downstream Penstock Invert877.5 (872.75)	
	Downstream Draft Tube Invert	855.5 (850.5)
d.	Reservoir (miles)	
	Length of Maximum Pool	6.7
	Length of Recreational Pool	5.7
	Length of Flood Control Pool	N/A
e.	Storage Design Values (acre-feet)	
	Normal Pool	12,300
	Flood Control Pool	N/A

1-4

Top of Dam		21,000
Design Surcharge	(difference between top of dam	8 700
Design Surenarge	and normal pool storage	0,700

# f. Reservoir Surface (acres)

Top of Dam	<u>1,020</u>
Maximum Pool	1,020
Flood Control Pool	<u>N/A</u>
Normal Pool	<u>710</u>
Spillway Crest	710

# g. Dam

Туре	Concrete Gravity Dam
Length of Overflow Section	440 feet
Length of Left Non-Overflow Section	ll7 feet
Length of Right Non-Overflow Section	243.5 feet
Length of Powerhouse	99.5 feet
Total Length of Dam	900 feet
Maximum Hydraulic Height	80 feet
Side Slopes	lv to 2.0 <u>+</u> h/upstream
Zoning	lv to 1.3 <u>+</u> h/downstream
Zoning	Clay placed upstream of core wall
Foundation	Bedrock
Impervious Core	Concrete
Slope Protection	Riprap

# h. <u>Spillway</u>

Туре	Uncontrolled overflow
Stilling Basin	30 feet concrete apron
Length of Overflow Section	440 feet
Crest Elevation	420.0 (915.0)
Gates	N/A
Upstream Channel	Lake with silt
Downstream Channel	Natural with some rubble

Ice Chute

# **Diversion Tunnel**

## Powerhouse

Spillway

A 10-foot wide bay on spillway adjacent to powerhouse. Has a drop grade that adjusts from Elevation 920.0 (915.0) to Elevation 908.0 (903.0).

 $6'_{\pm}$  high x  $5'_{\pm}$  wide tunnel through spillway. Invert elevation  $878_{\pm}$ ( $873_{\pm}$ ). Steel slide gate on upstream side. Gate has lifting chains extending up to steel bracket on crest of spillway. No hoist on site.

2 turbines. 7'-11" high x 9'-0" wide penstock intake. Headgate and stoplog control available at penstock intake. Wicket gate control at turbine. A third turbine pit is undeveloped.

Reportedly, 4 foot high flashboards have been used to control discharge. However, these have not been used in recent years.





TYPICAL SECTION

# SECTION 2 BACKGROUND ENGINEERING DATA

# 2.1 HISTORY

The Zumbro Lake Dam is owned by the City of Rochester Electric Department The dam is located approximately 18 miles north of Rochester in Wabasha County, Minnesota. The existing dam and powerhouse were constructed in 1919 for purposes of hydroelectric power generation. The dam remains essentially unchanged from its original configuration, however, repair work has been accomplished on the existing structure. The most significant modification to the structure has been the addition of a dewatering tunnel through the spillway section. This was accomplished during the 1961 repairs to enable the contractor to sufficiently lower the water level upstream of the dam to accomplish repairs to the upstream face. A gate was installed on the upstream side of this tunnel and a bracket which rests upon the crest is attached to the gate lift chains.

The following is an approximate chronology of major construction events associated with the dam:

- 1919 Construction of the existing Zumbro Lake Dam and powerhouse was completed.
- 1929 A gunite repair of the construction joints in the upper 14 feet of the upstream face of the spillway was accomplished.
- 1935 An overlay of the downstream face of the left half of the spillway was accomplished.
- 1961 A major renovation of the upstream face of the spillway. Much work was also done on the right half of the spillway crest. The dewatering tunnel was added during this renovation.

### 2.2 AVAILABLE DATA

The available data concerning the existing structure are as follows:

- a. A complete set of construction plans for the dam is on file at the City of Rochester Electric Department at the steam electric generating plant in Rochester. These plans were prepared by Hugh L. Cooper and Company Consulting Engineers, New York, New York. The drawings are dated in the years 1917 through 1919. The number of drawings in this set of plans are far too numerous to include in this report, however, copies of selected plans showing critical components of the dam are presented as Plates 2-1 through 2-21. The set of plans on file at the Rochester Electric Department include a full set of the original plans from which prints may be obtained.
- b. The operating records of the dam during its history are on file at the City Electric Plant in Rochester. These records contain water level readings, discharges and power produced at the hydro-electric plant.
- c. A report prepared by Harza Engineering Company, Chicago, Illinois, entitled "Repairs to the Hydro Plant Dam". This report is dated January 10, 1952. This report outlines several repairs required at the dam. A drawing showing areas of spillway deterioration is presented as Plate 2-22. This report also refers to an earlier report which was prepared by Mr. J. S. Bohman in 1933. The 1935 repairs were accomplished as a result of the report filed in 1933.
- d. A report filed with the City Electric Department by Mr. E. M. McGhie, P.E., who inspected the repairs to the dam in 1961. This report contains an abbrievated construction diary of events during repair of the dam and photographs of construction which are too numerous to include in this report. This report describes construction of the dewatering tunnel through the spillway.
- e. A memorandum for the record filed by the St. Paul District Office of the U.S. Army Corps of Engineers dated July 28, 1978 describes a brief inspection made of the dam during an estimated high discharge of 18,000

cfs. This report was filed in response to the observation of a reported crack in the dam. It was determined in this memorandum that this crack presented no hazard to the safety of the dam.

f. Volume I - Technical Proposal, Research Proposal submitted to the Department of Energy, Idaho Operations Office, Program Research and Development Announcement ET-78-D-07-1706. Feasibility Determination of Low-Head Hydroelectric Power Development at Existing Sites has been submitted for the Zumbro Lake Dam by the City of Rochester. This proposal was prepared by R. W. Beck and Associates, Seattle, Washington.

### SECTION 3

### HYDRAULIC AND HYDROLOGIC EVLUATION

## 3.1 AVAILABLE DESIGN DATA AND RECORDS

- a. A brief description of the Zumbro River watershed unit is presented in the Minnesota Department of Conservation, Hydrologic Atlas of Minnesota, Bulletin 10, April, 1959. This discussion includes such items as basin topography, climatology, stream flow characteristics, ground water and water supply.
- b. The lake areas in the watershed were found in the Minnesota Department of Conservation, Inventory of Minnesota Lakes, Bulletin 25, 1968.
- c. Although the U.S. Geological Survey did not maintain a stream gaging station at the Zumbro Lake Dam, the City of Rochester had maintained daily records at the dam from 1944 through 1969. The nearest continuous gaging station is located upstream on the South Fork Zumbro River near Rochester, and its years of record include 1953 to the present. The nearest downstream continuous gaging station on the Zumbro River is at Zumbro Falls with a period of record of June, 1909 to September, 1917, April to November, 1929 and March, 1930 to the present. The drainage area at the Zumbro Lake Dam is 810 square miles and the annual instantaneous peak discharges recorded at the dam are presented in Table 3-1.
- d. U.S. Geological Survey topographic maps were used to determine the drainage area upstream of the Zumbro Lake Dam. These topographic maps were also used to determine the area-volume curve and stage volume curve.

# 3.2 RUNOFF CHARACTERISTICS OF MAJOR FLOODS

The South Fork Zumbro River generally reaches its highest annual instantaneous peak discharges in the spring due to runoff caused from snowmelt or a combination of snowmelt and rainfall. Of the 26 annual instantaneous peak

3-1

discharges of record, it was determined that 14 annual instantaneous peak disharges occurred during the spring and 12 during the summer. Nine peak discharges were observed to occur in March, 5 in April, 2 in May, 4 in June, 2 in July, and 1 for each of the months of August, September, October and February.

The well-defined drainage pattern of the South Fork Zumbro River, which is developed on glacial drift, causes the runoff to be rapid. The average annual discharge on the South Fork Zumbro River at Rochester is 127 cfs or 5.67 inches of runoff over the watershed. The average annual discharge at the Zumbro Lake Dam is 390 cfs or 6.53 inches of runoff over the watershed. The average annual discharge of the Zumbro River at Zumbro Falls is 488 cfs or 5.86 inches of runoff over the watershed.

The highest flood on record at the Zumbro Lake Dam occurred as a result of intense rainfall in July, 1951. An instantaneous peak disharge of approximately 30,000 cfs occurred with a stage of 928.75 feet (dam datum). Another large flood occurred during July, 1978, when a peak discharge of approximately 18,000 cfs occurred with a stage of 2 to 3 feet above the crest. The 1951 flood corresponds to a probability of recurrence of 2% annually, or the flood that would occur on the average on once every 50 years. The 1978 flood corresponds to a probability of occurrence of 8% annually, or the flood that would occur on the average of 8% annually, or the flood that would occur on the average of 2% annually, or the flood that would occur on the average of 8% annually, or the flood that would occur on the average of 8% annually, or the flood that would occur on the average of 9% annually, or the flood that would occur on the average of 9% annually, or the flood that would occur on the average of 9% annually, or the flood that would occur on the average of 9% annually, or the flood that would occur on the average of 9% annually, or the flood that would occur on the average of 9% annually, or the flood that would occur on the average of once every 12 years.

#### 3.3 HYDRAULIC ASPECTS OF OPERATION PROCEDURES

The dam is an uncontrolled overflow spillway and has no formal documented hydraulic operating plan. There are two turbines for generation of hydro-power which could be used to control the lake level down to elevation  $889.0^{\pm}$ . The turbines can be controlled remotely at the City electric generating plant in Rochester. There is an ice chute gate which may be used for discharge, however, its capacity is very small and it has not been operated in recent years. There is a dewatering gate which was installed at the center of the spillway during the 1961 renovation. This gate cannot be opened except by a crane or special hoisting equipment.

# 3.4 CONSEQUENCS OF SUDDEN BREACHING BY OVERTOPPING OR STRUCTURAL FAILURE

Consequences of a failure of the Zumbro Lake Dam were analyzed for various flow conditions. The downstream impact of a sudden failure of the dam is highly dependent upon the flow condition. Specific cases are described below.

Case I - Failure of the spillway under normal operating conditions with a pool elevation of approximately  $915.0^+$ .

Case 2 - Failure of the spillway under high flow conditions with a pool elevation of approximately  $925.0^{+}$ .

Case 3 - Failure due to floods above elevation 925.0 approaching the magnitude of the Spillway Design Flood.

- a. Case I evaluates the effect of a structural failure of the spillway with a pool elevation of 915.0 and a tailwater elevation of aproximately 855.0. During this condition, it is possible to have little or no flow downstream of the dam. It is estimated that a maximum initial flood wave of approximately 26.7 feet would be propagated immediately downstream of the dam. It is also estimated that the maximum instantaneous discharge reached in the surge would be approximately 343,800 cfs. It is believed that the major energy of the surge would be dissipated in the channel and overbanks just downstream of the dam. The probability for loss of life and damage downstream of the dam as a result the failure is considered to be high.
- b. Case 2 evaluates the effect of structural failure of the spillway at high pool elevation of approximately 925.0. During this condition, the tailwater elevation due to the flood would be approximately 865.0. It is estimated that a maximum initial flood wave of approximately 26.7 feet would be propagated immediately downstream of the dam. It is also estimated that the maximum instantaneous discharge reached in this surge would be approximately 343,800 cfs. It is believed that the major portion of the energy of the surge would be dissipated in the overbanks and channel beyond the spillway of the dam. The probability for loss of life and damage downstream damage as a result of failure of this type is considered to be high.

Case 3 evaluates the effect of a failure of the dam by overtopping the c. abutments under high flow conditions with a pool elevation of approximately 925.0 or higher. For a dam of large size and high hazard, the Spillway Design Flood, as recommended by the Dam Safety Guidelines, is the Probable Maximum Flood. The Probable Maximum Flood peak discharge at the Zumbro Lake Dam is approximately 290,000 cfs. This flood is approximately six times the discharge capacity of the Zumbro Lake Dam. For a flow of 290,000 cfs, it is estimated that the headwater above the Zumbro Lake Dam would be near elevation 935.2 and the tailwater is estimated to be near elevation 883.0. In this case, the initial maximum flood wave resulting from a failure of the dam is estimated to be approximately 23.2 feet high, immediately downstream of the dam. The probability for loss of life and downstream damage is considered to be high. At flood levels near Elevation 930.0, it appears possible that the reservoir could overflow the west side of the reservoir upstream of the dam. This would create an emergency type spillway but would also cause flooding of residences along the flow path.

Table 3-2 summarizes the above cases.

# 3.5 RELATIONSHIP BETWEEN STRUCTURE AND OTHER DAMS ON THE SAME WATER COURSE

The Oronoco Dam is located 11.9 river miles upstream from the Zumbro Lake Dam on the Middle Fork Zumbro River. It is believed that a failure of the Oronoco Dam would probably have little effect upon the Zumbro Lake Dam. The Mantorville Dam is located 23.1 river miles upstream from the Zumbro Lake Dam on the South Branch Middle Fork Zumbro River. It is believed that a failure of the Mantorville Dam would have little effect on the Oronoco Dam and, therefore, a failure of the Mantorville Dam would have no effect upon the Zumbro Lake Dam. There are dams on the South Fork Zumbro River, upstream of the Zumbro Lake Dam. One is near the City electric generating plant in Rochester, the other dam is the Mayowood Dam southwest of Rochester. The Silver Lake Dam on Silver Creek, which is tributary to the Zumbro River, is also located in Rochester. Failure of any of these dams would not affect the Zumbro Lake Dam. There are no dams downstream of the Zumbro Lake Dam.

### 3.6 SUPPORTING DATA

- a. A discharge-frequency curve for the Zumbro Lake Dam was developed using discharges obtained from the Log Pearson Type III analysis. This curve is presented as Plate 3-1.
- b. A headwater rating curve was derived for various discharges using data obtained in the field. This curve is presented as Plate 3-2.
- c. A tailwater rating curve was developed from the information obtained in the field and is presented at Plate 3-3.
- A stage-volume curve and an area-volume curve were developed from the U.S. Geological Survey quadrangle maps. These curves are presented as Plates 3-4 and 3-5.
- e. A synthetic Probable Maximum Flood hydrograph for the Zumbro Lake Dam was developed by combining the synthetic Probable Maximum Flood hydrographs from the Middle Fork Zumbro River and the South Fork Zumbro River. These two synthetic hydrographs were computed using Synder's Method, and the final Probable Maximum Flood hydrograph is presented as Plate 3-6.

### 3.7 SUMMARY AND RECOMMENDATIONS

- a. The Zumbro Lake Dam does not meet accepted dam safety criteria because it is not capable of passing the Spillway Design Flood as recommended by the Dam Safety Guidelines. The Spillway Design Flood, as recommended by the Dam Safety Guidelines is the Probable Maximum Flood or 290,000 cfs. It is estimated that the overtopping discharge with turbines open is approximately 50,000 cfs corresponding to the flood with .035 percent probability of annual occurrence. The 100-year flood, or the flood with a 1 percent probability of annual occurrence has a discharge of 37,500 cfs, which can be passed without overtopping the dam. Therefore:
  - 1. It is recommended that a spillway design flood be determined on the basis of more detailed evaluations of the hydrologic, hydraulic and

downstream damage potential and that the modifications required to allow safe passage of the spillway Design Flood be implemented.

- b. The greatest hazard to the downstream area occurs during the failure of the spillway when the pool is at the normal elevation of 915.0.A failure under severe flood conditions would probably result in a high increase in the probability for the loss of life downstream of the dam. Overbank flooding from the high flow conditions would have already led to evacuation downstream of the dam, however, residences on the fringe of the flood area would be inundated by a sudden failure of the dam which would result in a high probability for loss of life. Therefore:
  - 1. <u>It is recommended</u> that a documented flood warning plan be developed for closing nearby bridges, evacuating nearby residences, and evacuating the downstream camping area during major floods.
  - It is recommended that detailed floodplain analysis be made downstream of the dam to determine the hazards to the camping area and local residences.
- c. No formal hydraulic operating plan was found to exist. Therefore:
  - 1. <u>It is recommended</u> that a documented hydraulic operating plan be developed and implemented for the spillway especially as it relates to the flood warning plan.

# TABLE 3-1

# ZUMBRO LAKE DAM INSTANTANEOUS PEAK DISCHARGES

Year	Peak Discharge
1969	8,925
1968	3,194
1967	7,478
1966	7,699
1965	14,759
1964	530
1963	4,143
1962	16,136
1961	9,911
1960	9,912
1959	5,527
1958	6,874
1957	2,542
1956	6,909
1955	1,184
1954	4,266
1953	5,920
1952	11,691
1951	11,120
1950	2,586
1949	6,249
1948	10,726
1947	4,148
1946	3,953
1945	13,552
1944	4,039

TABLE	3-2
-------	-----

Case	Discharge Over Dam cfs	Frequency of Occurrence* (%)	Headwater Elevation (ft.)	Tailwater Elevation (ft.)	Flood Wave Height (ft.)	Frequency of Potential Hazard
1	0		915.0	855.0	26.7	High
2	50,000	0.35	925.0	865.0	26.7	High
3	290,000	0.01	935.2	883.0	23.2	High

\*Note: The probability of occurrence of discharges with a probability of occurrence of less than 1 percent is estimated by interpolating between the Probable Maximum Flood (PMF) discharge frequency and the 1 percent frequency discharge. The PMF was estimated to have a probability of occurrence of .01 percent (i.e., the 10,000 year flood event).

				-		
	<u>A</u>	<i>#</i>	ROBABILITY X 2 LOG CYCLES REUFFEL & ESSER CO. MANNE IN UNA	Al Maria	46 8043	han har i
10	99.99	99.9 99.8 99	98 95 90 80 70	60 50 40 3	0 20 10 5 2	2 1 0.5 0.2 Carlado 0.00 pc
10. 9						
8						
7						
, ,						
6						
5		50000				
4		- CCCCDH				
3			Discharge + H	requency Cy	۳Ue	
2		2000				
	· · · · · · · · · · · · · · · · · · ·					
			┝ <del>┥┥┫</del> ╼╾┶╼╼┿╍┿╼┿╼┾╊╊┝┽╪╎╽╎┼╎╵┥╪┿┝	┶ <mark>╌┥╌┯╌╴</mark> ╍┲╼╞╍┇╍┨╍┨╍┥╍╍╍┥╴╏┈┤╌┯╼┑╌╗╼┨ ┑╴┱┈╽╼╌┈╡╶╴┑╴╴┑╴╎╴╎╺╎╴		
		4				
1.						
9.						
-7						
/		9-1				
6						
5		5000				
. 4						
3		305				
		┥╸╞╸┝╺┝┫ ╕╸┠╺┝╡┙╺╍╍╍╈╺╌┝┥╼╍╍╍┥╴╍╸┝╍╌┝╺╍┝╼╸┝╍┥╸┝╶╸┝ ╽┝┽╴╽╘╍╍╍╼╅┙╌┥╼╍╍╌╴┥╺╍┝╼╸┝╍┱╋╍╍┲╌┝╶┲╴				
			╞╪╪╢══┼═┾╌┨═┼╶╞╞╎╱╎┼╢╵┾╢╶╤╎┼╎╞			
2						
2						
		+		$\sim$		
				┽┼┿┽┥╊┯┥┾┿╊┿┿┙┝┩╶╌╸┟╌┨		<mark>┟┼╎┽┼┼╶╢╎┼╎┼╪╷╷┽┈┑┥┈┑┥</mark> ╴
				April 1 0	rience Paraeut	┠╎┤┾┝┲╎╎┼┼┝┲┼╍╌┼
		┊┼╎╢╾┥╴┨╼┽╼┤╶┤┾┿┿┥┨┥		+++++++++++++++++++++++++++++++++++++++		
1	1					

3-1

PLATE



1. M.N.

8 2

L

S

NO. 340R-20 DIETZGEN GRAPH PAPER 20 X 20 PER INCH

DIETZGEN CORPORATION MACH IN U. S. A.



PLATE ω 1

ω



ND. 340R-20 DIETZGEN GRAPH PAFER 20 X 20 PER INCH S. A.

DIETZGEN CORPORATION

					╺┼╽┿┿┿╷╢┝╎┼┢╎┾╓╎┿╓╎╴┿	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	
Here's	a- Volume C	4 <b>70</b> 0					
					+++1		
n ser ser					╾ <mark>╴┣╶┧╴┝╶┿╸┥╶┶┝╶┼╼┥┲╴╹┍┶┍┝┍┥┍╸</mark> ┤ ┯┶╍╕╾┙┙┙┙┍┍╸┥┑╼╴╵┿╸╵┥┿ ┯╴┨╺┦╷╕┝╌┩╽╴╱┍╸┨┑┑╸╕		
					╪┧┽╴┾╖╡┶╷╴┾┝┿┥┿╍┞		
φ 500	10583	15000	20000	25000 30		35000	
		Storage	Acre-Fo	89.C	┆╎╎┆╎┆╎┼┥╎┾┥╅┿╪┿ ┆╎╎╷╡╪╵╡╪╵┿╴┿╋╵┿╇┿┿ ╪┼╎┝╕┿┲╸┝┲╴╵┲╴╵		
		U-					

NU. 04UR-20 DIETZGEN BRAPH PÁPER 20 x 20 per inch

\*

.

PLATE

မ - ပ •

April 1

DICTZGEN CORPORATION

ALCONCH.

يخاص

.



# SECTION 4 EVALUATION OF PHYSICAL ASPECTS OPERATION AND MAINTENANCE

### 4.1 **RESPONSIBILITY**

The City of Rochester has responsibility for operation and maintenance of the Zumbro Lake Dam. The City Council has the authority to obtain maintenance and proper engineering when required. The City of Rochester Electrical Department is responsible for day to day operation of the dam and has personnel who are responsible for the dam.

### 4.2 OPERATION

This section deals with the ability of the structural and mechanical components of the dam to function as originally intended. The hydraulic implication of the operating procedures is discussed in Section 3. The existing operable facilities at the dam consists of two turbines in the powerhouse, an ice chute located at the right side of the powerhouse, and a gated dewatering tunnel located approximately in the middle of the spillway. The penstocks are controlled by headgates which are reportedly operational. These headgates are operated by hand, but a portable motorized drive unit was available to supply shaft power for gate hoists. There are also stoplog slots at the penstocks and stoplogs and equipment for their installation and removal are present at the site. The discharge through the turbines is controlled by the gates on the turbines. These gates are remotely controlled from the electric generating plant in Rochester, but with respect to flood flows, the discharge capacity of these turbines is small. At this time, it is doubtful as to whether the ice chute gate can be operated because it reportedly has not been operated in recent years.

# 4.3 MAINTENANCE

At this time, there is no formal documented maintenance program for the Zumbro Lake Dam. The City Electric Department of Rochester periodically visits the site to inspect and maintain the electrical generation equipment inside the powerhouse. The need for maintenance for the remainder of the dam is apparently based upon visual observations.

### 4.4 INSPECTION

An on-going maintenance program is essential to the integrity of a water retaining structure such as the Zumbro Lake Dam. The basis for such a maintenance program should consist of an informal and formal program of The informal program is often the most important and requires inspection. operating personnel who are conscious of the normal day to day condition of the structure and of specific features which have been identified as potential problems. This procedure wold allow any changes in site conditions to be noted and evaluated ina timely manner. The formal aspect of a continuing inspection program should consist of a regularly scheduled systematic inspection of the features of the structure. Such inspections usually involve formal documentation and, in some cases, photographs of the structure. Such an inspection provides a frame of reference for evaluating future changes in the condition of the structure. The recommended frequency for formal inspections is annually and during or after every instance of unusually high water or high wave conditions. A comprehensive inspection program currently does not exist for the Zumbro Lake Dam. However, the Rochester Electric Department does inspect the dam on an irregular basis.

# 4.5 SUMMARY AND RECOMMENDATIONS

The Zumbro Lake Dam currently functions primarily as an uncontrolled spillway although there is flow through the turbines which is controlled by the City of Rochester Electric Department. Operation of the other outlet strucutres has been very infrequent. Therefore:

1. <u>It is recommended</u> that a documented program of inspection and maintenance be developed and implemented. The inspection program should be designed to detect deficiencies related to seepage, scour and structural distress.

4-2

# SECTION 5 GEOTECHNICAL EVALUATION

# 5.1 AVAILABLE SUBSURFACE DATA

The available subsurface data is listed in Section 2 of this report and consists of:

- a. Soil borings performed in 1916 by Hugh L. Cooper & Co. along the proposed centerline for the Zumbro Lake Dam.
- b. Shallow hand auger borings and visual observations by Barr Engineering Co. during the current dam safety inspection program together with published information.

# 5.2 GENERAL GEOLOGY

The Zumbro River drains the majority of Dodge, Olmsted, and Wabasha Counties and parts of Goodhue County. The land surface features of the area ranges from a fairly level till plain at the west end of the watershed to deeply incised river valleys at the eastern and northern parts of the basin. Elevations range from a high of more than 1,300 feet MSL in the western part of the watershed to elevations below 900 feet in the Zumbro River valley.

The western end of the watershed consists of glacial drift deposited from the Nebraskan, Kansan and Iowan glaciations, which is over 100 feet thick at places. The eastern and northern parts of the basin are predominantly loess ranging in thicknesses from 0 to 100 feet. Alluvial deposits, up to 75 feet in thickness, occur along the stream valleys, especially the Zumbro River valley.

The bedrock formations underlying the basin range in age from Pre-Cambrian to Upper Ordovician. The sedimentary rocks, including those of the Pre-Cambrian, have a total thickness of over 3,500 feet. Outcrops of the various rock formations can be seen quite easily along the Zumbro River Valley.
### 5.3 SITE GEOLOGY

Exposed rock outcrops are numerous at the site of the Zumbro Lake Dam. Sandstone seems to be the predominant type of rock found along the base of the dam and along the valley walls up to the crest of the dam. This sandstone is probably a member of the Prairie-du-Chien group. The sandstone found on the downstream apron has the characteristics of the Jordan sandstone. This sandstone is light brown in color and is fairly well cemented. Shallow hand auger borings and visual observations showed that bedrock was at or near the surface on the valley floor and on the sides of the abutments. The tops of the bluffs in the area above the dam seemed to be capped with a grayish dolomite and is probably a member of the Oneota-Shakopee formation. Alluvial deposits were quite noticeable downstream of the dam, with numerous sandbars and sand plains common in the area.

#### 5.4 EXISTING STRUCTURE

The existing structure consists of a left non-overflow section, powerhouse, 440foot long overflow spillway, and right non-overflow section. The entire structure was placed on grouted sandstone bedrock, as observed in the field and as noted on the construction plans and borings. The following paragraphs describe major components of the dam.

#### a. Spillway

The spillway, ranging in heights from 43 to 55 feet, is an uncontrolled overflow ogee spillway constructed of mass concrete. The spillway is abutted on the right by a concrete abutment wall and on the left by the powerhouse. An ice chute is located on the spillway adjacent to the powerhouse. The ice chute gate appears to be in fair condition; however, it has reportedly not been operated in recent years. A typical spillway section is presented as Plate 1-3.

The spillway has a downstream apron extending approximately 30 feet beyond the end of the ogee. The apron elevation varies as it is stepped to match the downstream elevations of the ogee sections. At the right half of the spillway, the water flows past the end of the apron and onto a large sandstone outcrop, which extends approximately 50 feet beyond the toe of the apron. The top of this outcrop is approximately 15 feet above the downstream channel of the Zumbro River. The left half of the spillway has a concrete apron which was submerged under approximately 7 feet of water at the time of the inspection.

#### b. Powerhouse

The powerhouse substructure and superstructure are constructed of concrete. The powerhouse has three turbine pits, however, only two turbines were installed and are presently functioning. The powerhouse has a trashrack, penstock with a headgate, scroll case, draft tube and tailrace for each turbine installation. The penstock intake also has stoplog slots which may be used to block flow to the turbine. The turbines have wicket gates which are remotely controlled from the electric generating plant in Rochester. The powerhouse has a derrick and other appurtenances necessary to install and remove stoplogs. The hoisting mechanisms for the headgates are in place and appear to be functional. Downstream of the powerhouse, a concrete training wall extends outward between the powerhouse tailrace and the spillway, while nearly vertical exposed bedrock exists at the left of the tailrace. The powerhouse is presented in Plates 2-1 through 2-3 and Plates 2-9 through 2-11.

#### c. Non-Overflow Sections

The right non-overflow section starts at the right abutment as a 5-foot thick core wall keyed in the bedrock with adjacent earthfill for approximately 170 feet. The remaining 75 feet of non-overflow section is a mass concrete gravity dam. The right non-overflow sections are presented in Plates 2-14 through 2-17. The earthfill slopes in the core wall section are steep and have trees growing on them. The earthfill consisted of a thin cover of topsoil covering a rocky fill. There is no earth backfill at the gravity dam section until approximatley one-third of the way down its downstream side. Numerous bedrock outcrops were noticed near the toe of the downstream slope of the right non-overflow section.

5-3

The left non-overflow section starts at the powerhouse and ends at the left abutment. This section consists of a mass concrete gravity dam founded on and keyed into bedrock. The left non-overflow section is presented in Plates 2-7 through 2-8. Numerous bedrock outcrops are visible along the side of the hill into which this section terminates.

#### 5.5 ASSESSMENT OF FOUNDATION AND SLOPE STABILITY

There is no record of formal stability analysis of the Zumbro Lake Dam. No signs of foundation instability such as cracking of the concrete or large displacements were observed on the dam. Since the dam abutments incorporate massive concrete core walls embedded in bedrock, the slope stability of the earth embankments placed against the core walls was not applicable. Failure of an earth slope would not create a hazard to the dam. Erosion did not seem to be a major problem due to the shallow bedrock depths on both abutments. The construction plans indicate that the dam is keyed quite deeply into bedrock. This probably also indicates that much bedrock was excavated to find competent rock for the dam foundation. The dam would probably meet current criteria with respect to foundation stability.

# 5.6 ASSESSMENT OF SAFETY OF STRUCTURE AGAINST UNCONTROLLED SEEPAGE

Only minor seepage was observed on both abutments. The spillway was damp from water which had been previously running over the crest and from rainfall that occurred the morning of the inspection, making it impossible to determine the extent of seepage through the spillway. In 1935 and 1961, repairs were made on the spillway to seal the seepage that had been flowing through the construction joints. Minor seepage was also observed to be exiting from the upstream wall on the interior of the powerhouse. Seepage observed at the dam was extremely small in quantity and did not indicate any major piping or erosion problem, which would be detrimental to the stability of the dam.

#### 5.7 SLOPE PROTECTION

The right abutment was protected with riprap, however, heavy tree growth in this area could be detrimental to the riprap if the trees were uprooted in a storm causing a break in the riprap protection and leading to possible erosion. The left abutment banks have been heavily eroded resulting in near vertical slopes.

#### 5.8 SCOUR PROTECTION

The existing energy dissipation works consists of a downstream apron. The material downstream of the apron is a sandstone which may be somewhat condusive to scour. There is no history of scour problems at the dam. The dam is set rather deeply into bedrock, however, unchecked scour chould eventually cause a hazard to the stability of the dam. During the field investigation, soundings indicated a 14 foot deep scour hole approximately 50 feet downstream of the highest spillway section.

#### 5.9 CONCRETE AND MASONRY CONDITIONS

The concrete, in general, seems to be in good condition. Spalling and minor cracking were observed on the non-overflow sections, however, this deterioration does not pose a hazard to the safety of the dam. Repairs were made in 1935 and 1961 to replace and repair several sections on the upstream and downstream slope of the spillway. The right half of the spillway is severely eroded in areas, however, the spillway is constructed of mass concrete and the stability of the structure is not affected by this deterioration. The surface condition of the powerhouse concrete and the spillway overlay concrete appear to be in good condition with minor spalling noted. The upstream face of the spillway was submerged and the condition of the concrete could not be observed. Cracks were observed at the top of the archways within the powerhouse. This cracking is discussed in Section 6.

#### 5.10 SUMMARY AND RECOMMENDATIONS

The following conclusions and recommendations are made regarding the foundation of the Zumbro Lake Dam and powerhouse:

a. This dam has a past history of seepage through the construction joints in the concrete spillway although construction repair took place in 1935 and 1961 to repair this situation. Therefore:

- 1. <u>It is recommended</u> that, during periods of low-flow when the spillway surface is dry, that an inspection be made to determine the extent of seepage through the spillway.
- b. Both abutments have a considerable amount of tree growth. However, it is not recommended that these trees be removed upstream of the concrete core wall because the massive concrete core walls and mass concrete nonoverflow sections of the dam would not be adversely affected by tree growth. There is some severe erosion occurring on the upstream banks near the left abutment. Therefore:
  - 1. <u>It is recommended</u> that the banks upstream of the left abutment be stabilized and the trees removed from the riprap on the banks upstream of the right abutment.
- c. Based on soundings downstream of the apron:
  - 1. <u>It is recommended</u> that the scour holes should be periodically sounded to insure that unchecked scour does not lead to possible stability problems.

# SECTION 6 STRUCTURAL EVALUATION

## 6.1 BACKGROUND DATA

d.

The available data consist of the following information:

- a. A complete set of construction plans for the dam is on file at the City of Rochester Electric Department, steam electric generating plant in Rochester. These plans were prepared by Hugh L. Cooper & Company, Consulting Engineers, New York, New York. The drawings are dated in the years 1917 through 1919. The number of drawings in this set of plans are far too numerous to include in this report, however, copies of selected plans showing critical components of the Dam are presented in Section 2.
- A report prepared by Harza Engineering Company, Chicago, Illinois entitled "Repairs to the Hydro Plant Dam". This report is dated January 10, 1952. This report outlines several repairs required to the dam. This report also refers to and has excerpts from an earlier report which was prepared by Mr. J. S. Bowman in 1933.
- c. A report filed with the Rochester Electric Department by Mr. E. M. McGhie, P.E., who inspected the repairs to the Dam in 1961. This report contains an abbreviated construction diary of events during construction of the Dam and photographs of construction which are too numerous to include in this report.
  - A memorandum for the record filed by the St. Paul District Office of the U. S. Army Corp of Engineers dated July 28, 1978, describes a brief inspection made of the dam made during an estimated high discharge of 18,000 cfs. This report was found to be in response to the observation of a reported crack in the Dam.

#### 6.2 ASSESSMENT OF STRUCTURAL STABILITY

Examination of the Zumbro Lake Dam indicates that structural stability is acheived by use of mass concrete which resists sliding and overturning forces by gravity. The construction plans indicate that the mass concrete sections of the Dam are embedded in the bedrock, however, it appears that no intentional keyway into the bedrock was constructed. Most of the bedrock excavation was probably performed to remove fragmented or soft bedrock material. There is no anchorage to the bedrock other than the frictional resistance along the structure and bedrock interface. The construction plans for the spillway section of the Dam indicate that grout pipes were extended into the bedrock foundation below the mass concrete ogee section. Inspection of the upstream gallery at the base of the powerhouse substructure indicated that the ground pipes were installed and the grouting accomplished. No record of this grouting, however, has been located. The plans also indicate that the spillway apron contains drain holes and is anchored to the bedrock with reinforcing steel drilled 15 feet deep into the bedrock. The channel downstream of the structure is exposed bedrock and it appears that it is performing well with respect to scour and there appears to be no undercutting of the structure. The left non-overflow mass concrete section extends to the bedrock at the left abutment and the construction plans indicate that it is keyed deeply into the bedrock abutment. The right non-overflow mass concrete section extends approximtaely 75 feet beyond the end of the spillway section. From the end of the mass concrete section to the right abutment, the nonoverflow section has a rather massive core wall which is approximately 5 feet thick. This core wall is keyed deeply into bedrock with mass concrete completely filling the keyway below Elevation 902 (dam datum). Earth fill is placed upstream and downstream of this core wall which greatly adds to the overturning and sliding stability of this core wall. The slopes of this earth fill are rather steep, however, a failure of these slopes would not present a hazard to the dam. This core wall is also keyed into the bedrock at the right abutment of the dam.

No existing design calculations for stability were found to exist for the Zumbro Lake dam. The set of construction plans for the dam, however, do provide valuable information regarding the foundation of the dam and cross sections of its structural members. No design loadings or structural strengths were noted on the plan sheets. Visual observations of the structural components of the Zumbro Lake dam indicate that there is no evidence of stability problems. The mass concrete sections of the Dam appear to be stable with no displacements or large cracks noted. There is severe detoriation of the concrete surface on the right half of the downstream face of the spillway, however, this detoriation probably does not affect the overall stability of the Dam. There has been a history of seepage problems along the construction joints of the mass concrete sections. Attempts to repair these leaks have been made and no displacement appears to have taken place along these joints. The left and right mass concrete non-overflow sections appear to be stable because no cracking or evidence of movement was observed. The thick concrete core wall at the right nonoverflow section appears to be stable with no movement or cracking observed along its exposed top surface.

Cracks were observed in the crowns of the second tier of arches on the upstream side of the powerhouse. The line of these cracks run parallel to the line of the dam. Cracks were also observed in the crowns of the arches above window sections near the corners of the powerhouse and at the center of the powerhouse. There is one expansion joint which runs near the center of the powerhouse which appears to be functioning properly. There appears to be no progressive detoriation occurring along these cracks as there is no additional cracking extending from them and little or no spalling around the cracks. The cracks appear to be primarily in the range of 1/8 inch to ¼ inch in width, their widest part at the crown of the arch. However, there are a few cracks which would probably range from 3/8 inch to ½ inch wide.

The cracks in the powerhouse are probably due to differential movement due to temperature expansion and contraction. The powerhouse structure is attached to a large mass concrete section of the dam which contains the turbine penstocks. This mass concrete section probably undergoes little expansion and contraction while the powerhouse section, with a large surface area exposed to varying temperatures, undergoes larger movements due to temperture variations. These movements have probably resulted in the cracking evident inside the powerhouse. A similar situation has probably caused a crack in the operating platform above the ice chute gate. It is reported that these cracks have existed for at least 20 years and probably longer. The powerhouse structure below the turbine level appears to be very stable with no cracking or differential movement observed. Inspection of the gallery along the bottom of the mass concrete section in the powerhouse indicates that no cracking or differential movement deep within the section along the foundation has occurred.

The past peformance of the structure is good. There are no reports of stability problems occurring due to large loadings as the result of hydraulic or ice loadings. The Zumbro Lake dam maybe subjected to large ice loadings because of its vertical upstream face, long narrow reservoir and the fact that power production at the dam will probably keep the water level slightly below the level of the crest during low winter flow. On July 6, 1978 the Dam was subjected to high flows due to severe flooding on the south fork of the Zumbro River upstream of the Dam. At this time, the crack in the operator's platform of the ice chute gate was observed by visting personnel at the site and was thought to be a hazard to the safety of the Dam. However, subsequent inspection by Corps of Engineers personnel and others indicated that this crack existed prior to the flooding at the dam. A city employee with the Electric Department indicated that this crack has been present for many years and has shown no additional detoriation or movement. The cracking around the ice chute operator's platform

Sliding and overturning stability calculations were performed on a critical section through the spillway. This critical section is the highest part of the spillway adjacent to the powerhouse. The stability of this section was examined when subjected to loadings due to hydrostatic pressure at a pool level at the crest (greatest differential head), ice, silt and uplift. The ice force was assumed to be 10,000 pounds per linear foot. The silt load is relatively low due to the fact that the soundings upstream indicated that no significant siltation has occurred at the dam. The relatively long narrow reservoir causes much sediment to settle before it is carried to the Dam, therefore, it is possible that the service life for the structure will be reached before significant siltation has occured along the upstream face of the dam. The uplift force along the base of the dam was assumed to have a triangluar distribution with a maximum pressure equal to the head on the dam at the upstream side to near zero at the downstream toe. The forces stablizing the section are the weight of the section and the frictional

force developed along the concrete bedrock interface. A fiction factor of 0.5 was assumed for the interface. The contribution to stability by the tailwater or resistance from the downstream edge of the spillway keyed into bedrock was neglected for these stability computations.

The loading cases examined and the resulting sliding and overturning safety factors are presented as Table 6-1. This sliding and oveturning analysis is not to be considered as in-depth analysis and the purpose of this analysis is to indicate the relative stability of the dam. Examination of Table 6-1 indicates that several safety factors are below those required by recommended dam safety criteria. However, it is believed that the analysis conducted is conservative. Therefore, it is concluded that the safety factors with respect to overturning would probably satisfy the required dam safety criteria. It is also concluded that the dam would probably have an adequate factor of safety against sliding even though it may not satisfactorily meet design criteria.

#### 6.3 ASSESSMENT OF STRUCTURAL STRENGTH

The majority of the Zumbro Lake Dam is a mass concrete structure with much of the spillway section being 60 feet high and approximately 70 feet wide at the The spillway apron is 3 feet thick and is anchored to the bedrock base. foundation. The retaining walls along the spillway and the concrete core wall at the right nonoverflow section are 5 feet thick which appears to be adequate for the loading conditions. The concrete components of the powerhouse superstructure appear to be relatively thick. The thinnest wall section appears to be in the range of 18 inches with column and arch sections being greater than 30 inches in thickness. The slabs supporting the first walkway tier and the main floor of the powerhouse appear to have a minimum thickness of 18 inches. This system appears to be more than adequate to support the applied loads. The roof of the powerhouse is a steel truss with a concrete roof slab. This roof structure The upstream side of the appears to be adequate and in good condition. powerhouse is a large mass concrete section which contains the turbine pen-These sections appear to be in good condition with no signs of stocks. The cracks within the detoriation due to inadequate structural strength. powerhouse appear to be due to temperature variations and not due to overloading of the powerhouse structural components.

The no existing structural strength calculations were found to exist for the Zumbro Lake dam. Also, no indications as to the required structural strength of the material components of the dam were found to exist on the construction plans.

Visual observations of the structural components indicate that there appears to be no severe cracking, deflections or material detoriation that would present a hazard to the safety of the Dam. No exposed reinforcing steel was noted in the structure. There is possibly a local failure in the area of the ice chute pier and operator's platform. Severe cracking has occurred through the operating platform's slab and through the pier so that it is possible that the pier and platform may become severed from the main Dam structure. This condition does not present a hazard to the safety of the Dam, however, it does present a safety hazard to operating personnel and the public using the downstream area.

There are no reported problems which would indicate failure of the dam structure materials to meet recommended design criteria. There is a history of structural repairs due to seepage through the construction joints in the main spillway, some of which were probably successful in sealing off some of the seepage or slowing down the deterioration of the concrete. Review of the structural features of the Zumbro Lake Dam indicate that is is probably stable and may meet current recommended design criteria for structural materials. This is based upon judgment as to the adequacy of the structural members based upon a review of the existing construction plans and visual observations made in the field. No calculations are available upon which to make conclusions regarding structural strength.

#### 6.4 EVALUATION FOR THE NEED FOR ADDITIONAL STUDY

A phase II level stability analysis or structural strength evaluation is not currently available for the Zumbro Lake Dam. Section 3.6.1 Recommended Guidelines for Safety Inspection Dams" states that a Phase II level stability analysis should be on record for all dams in the high hazard category or large dams in the significant hazard category. Therefore, additional study would be required to place in the record a stability analysis which examines the Zumbro Lake Dam with respect to dam safety criteria. This recommendation does not indicate that there is a stability problem, rather that the results of this investigation, due to its limited scope, are inconclusive and that the structural stability of the Zumbro Lake Dam should be examined in more detail.

#### 6.5 SUMMARY AND RECOMMENDATIONS

The Zumbro Lake Dam would probably meet current recommended design criteria with respect to overturning stability. The dam probably does not meet current recommended design criteria with respect to sliding stability, however, its stability with respect to sliding is probably satisfactory. The structural strength of the Zumbro Lake Dam structural components may meet current recommended design criteria. Severe deterioration of the right half of the spillway surface was observed, however, this does not present a hazard to the structural stability of the dam but may lead to accelerated concrete deterioration or hydraulic inefficiency. Therefore:

- 1. <u>It is recommended</u> that the severe spillway surface deterioration be repaired in the near future.
- 2. <u>It is recommended</u> that additional study be performed to conclusively evaluate the stability of the Zumbro Lake Dam.
- 3. <u>It is recommended</u> that the cracks in the powerhouse superstructure be repaired to prevent possible accelerated deterioration.

# TABLE 6-1

# STABILITY OF ZUMBRO LAKE SPILLWAY\*

Loading Case	Sliding Safety Factor	Overturning Safety Factor
a. Normal Pool, No Ice, Silt, or Uplift Pressure	1.48	5.21
b. Normal Pool with Silt. No Ice, or Uplift Pressure.	1.10	4.02
c. Normal Pool With Silt or Ice Pressure. No Uplift Pressure.	1.38	4.34
d. Normal Pool With Silt and Ice Pressure. No Uplift Pressure.	1.04	3.44
e. Normal Pool With Silt, Ice and Triangular Uplift Pressure.	0.60	1.37
f. Normal Pool with Triangular Uplift Pressure.	0.83	1.59
g. Non-overflow Section With Ice Load and Normal Pool	1.37	3.12
h. Spillway Section With Normal Pool and Ice Load With 17' Deep Scour Hole.	1.15	· · · ·

\*Effect of Bedrock Key Neglected.

APPENDIX A

٦

REPORT OF FIELD INSPECTION

#### CHECKLIST

This checklist contains information obtained from visual observations on the day of the inspection. It is not intended that specific information in the checklist coincide exactly with the main report. Further study during preparation of the report may significantly alter previous judgements and conclusions as noted in the checklist.

## NATIONAL DAM SAFETY PROGRAM

## GENERAL CHECKLIST

This form should be filled out by the team leader but should represent a consensus of the opinions and input of all team members.

1.	a. Name of Dam Zanders Lake Dury
	b. I.D. Number <u>· 358</u>
2.	Date of Inspection <u>Nuy 22</u> , 1979
3.	Name or owner <u>City of Rochester</u>
4.	Location County Wabusha
	Township <u>OQ N</u> Range <u>INE</u> Section <u>27</u>
5.	Is location shown on county map; or U.S.G.S. Quadsheet?
	<pre>( ) Yes (correctly) ( ) Yes (incorrectly) ( ) No - show correct location</pre>
6.	Are items on inventory sheet correct?
	<ul> <li>( ) Yes (information is all correct)</li> <li>(√) Yes (corrections attached)</li> <li>( ) No (completed form attached)</li> </ul>
7.	Type of dam (check all appropriate)
	<ul> <li>( ) Earth and/or rockfill (use form a)</li> <li>( ) Concrete and /or masonry (gravity) (use form d)</li> <li>( ) Other Explain</li> </ul>
8.	Year of construction 1917 1919
9.	Year(s) of major rehab1933-35, 1951-52, 1961
10.	Purpose of dam (chèck all appropriate)
	<ul> <li>Flood Control</li> <li>Water Supply</li> <li>Hydro Power</li> <li>Recreation</li> <li>Navigation</li> <li>Other Explain</li> </ul>

11. Pool el. on day of inspection <u>414.75</u>

12. Tailwater el. on day of inspection \_\_\_\_\_\_\_

13. Type of spillway and/or outlet (check all appropriate)

<u>Controlled</u>	Uncontrolled	Type	
( ) ( ) ( )		Pipe or Conduit Chute or notch Overfall Other Explain	

14. General description of operating procedures. (Is there any formal documented hydraulic operating plan? If so, who operates?)

No Formal documented operating procedure. Down is controlled informatically From city electric plant. Down operator From city of Rochester visits the plant about once a week.

15. Is there any program of regular systematic inspection and maintainance? If so describe.

No formal systematic inspection or maintanance. Informal and regular inspection performed by city personnel.

#### 16. Do the following exist?

Yes Don't Yes, Not Inclosed Inclosed No Know Where Design data Plans and specs Shop drawings As builts 0 & M Manuals History of const photos Remarks <u>Complete set of plans on file ut city of</u> <u>Rochaster electric plant</u>. Is there any formal flood warning system at the dam other than notification by local authorities? ( ) Yes, () No, Remarks 18. Is there any evidence that the dam has ever been overtopped? No ) High water marks ) Erosion ) Evidence of repair ) Verbal reports ) Other Explain 19. Estimate the degree of lake siltation. ( ) No noticeable siltation in lake (1/) Some minor amount of siltation ( ) Lake has major amounts of siltation ) ( Lake is completely silted in • Remarks . • · · · ·

Loss Of Economic Type of Improvement Life Loss (indicate number) Potential Potential Remarks 20. . . . likely Above Stream (ft.) (miles) Agricultural Building number) Unoccupied dwelling Industrial Building 4 Possible, but not Occupied dwelling than less Distance Building A \$ more оц \$ \$ Ht. to Urban Area Dam (give than than 4 Railroad Approx. Valley Likely Other Likely Other Less More Road ŝ Compyround, 1/8 mi. downstream Ч 5.1 Ţ 4) つこと °C3<sup>,</sup> 5.7-7: C.1 C.S.A.H 7 Brilge 1.5 Confluence with N.F. Zumbro R. , 1 12 Confluence with Mississippi R.

LIST OF POTENTIAL DOWNSTREAM HAZARD

57777775755319765315575

-

21. The above list was ended because:

( ) We do not feel that points further downstream are seriously threatened by the dam
( ) We have already established a very high downstream hazard, but further downstream hazard exists
( ) We cannot tell, further study is needed
( ) Other Explain

22. Give your overall opinion of the downstream hazard potential.

Team member	1. High	2. Significant	3. Low	Can't Decide
D. Zuelle	( )	( )		()
C. Reim	( )	( )	()	()
	(5)	( )	( )	

Loss of Life (Extent of Development)

None expected (No per-

manent structures for

human habitation)

More than few

Low

High

Category

Significant

(Extent of Development)

Economic Loss

Minimal (Undeveloped to occasional structures or agriculture) Few (No urban develop-<br/>ments and no more than<br/>a small number of<br/>inhabitable structures)Appreciable (Notable<br/>agriculture, industry<br/>or structures)

Excessive (Extensive community, industry or agriculture)

23. Are there any floodplain regulations or other constraints in force which would limit future development or future hazard downstream?

No Yes	Describ	e		
<u></u>	<b>`</b> -	<u></u>		
	****	· · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · ·	• • • • • • • • •
• • • • • • • • • • • • • • • • • • • •				· · · · · · · · · · · · · · · · · · ·
		· · · · · · · · · · · · · · · · · · ·		

24. Is there any development in the emergency spillway area which may suffer damage due to flow through the spillway?

7

Yes, Describe	(√) ()	N/A No emergenc	- <b>J</b>				
Check which item best describes the condition of the channel upstream of the lake. ( /) Clear of debris, trees, etc. ( ) Some minor debris in channel and a few trees periodicall in channel ( ) Much debris in channel and many trees in channel ( ) Much debris in channel and many trees in channel ( ) Channel completely blocked by debris and trees Remarks Remarks Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( ) Weirs, etc. ( ) Other Explain kuch mande the dam.	ćś	Yes, Describe			· · · ·		•
Check which item best describes the condition of the channel upstream of the lake. ( /) Clear of debris, trees, etc. ( ) Some minor debris in channel and a few trees periodicall in channel ( ) Much debris in channel and many trees in channel ( ) Much debris in channel and many trees in channel ( ) Channel completely blocked by debris and trees Remarks Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( /) Piezometers ( ) Weirs, etc. ( ) Other Explain Water level manometer made the dam				•••			
Check which item best describes the condition of the channel upstream of the lake. ( /) Clear of debris, trees, etc. ( ) Some minor debris in channel and a few trees periodicall in channel ( ) Much debris in channel and many trees in channel ( ) Much debris in channel and many trees in channel ( ) Channel completely blocked by debris and trees Remarks Remarks Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( ) Piezometers ( ) Weirs, etc. ( ) Other Explain here the manometer inside the dam	·:	- ``	· · · · · · · · · · · · · · · · · · ·				
Check which item best describes the condition of the channel upstream of the lake. ( /) Clear of debris, trees, etc. ( ) Some minor debris in channel and a few trees periodicall in channel ( ) Much debris in channel and many trees in channel ( ) Much debris in channel and many trees in channel ( ) Channel completely blocked by debris and trees Remarks Remarks Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( ) Piczometers ( ) Weirs, etc. ( ) Other Explain Water level manometer made the dam							
Check which item best describes the condition of the channel upstream of the lake. ( /) Clear of debris, trees, etc. ( ) Some minor debris in channel and a few trees periodicall in channel ( ) Much debris in channel and many trees in channel ( ) Much debris in channel and many trees in channel ( ) Channel completely blocked by debris and trees Remarks Remarks Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( ) Piezometers ( ) Weirs, etc. ( ) Other Explain Water level manometer inside the dam							
<ul> <li>Check which item best describes the condition of the channel upstream of the lake.</li> <li>( ) Clear of debris, trees, etc.</li> <li>( ) Some minor debris in channel and a few trees periodicall in channel</li> <li>( ) Much debris in channel and many trees in channel</li> <li>( ) Much debris in channel and many trees in channel</li> <li>( ) Much debris in channel and many trees in channel</li> <li>( ) Channel completely blocked by debris and trees</li> <li>Remarks</li> </ul> Are there any type of instruments on the dam? <ul> <li>( ) No</li> <li>( ) Monumentation</li> <li>( ) Piezometers</li> <li>( ) Weirs, etc.</li> <li>( ) Other</li> <li>( ) Explain but the lower mande the dam</li> </ul>	Chock	which it on boot	docariboc	the condit	ton of +1	o oher	 
<pre>( /) Clear of debris, trees, etc. ( ) Some minor debris in channel and a few trees periodicall in channel ( ) Much debris in channel and many trees in channel ( ) Channel completely blocked by debris and trees Remarks Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( ) Piezometers ( ) Weirs, etc. ( ) Other Explain ketel manometer inside the clan</pre>	upstr	eam of the lake.	describes	the condit	TOU OF LI	ie chant	IGT
<ul> <li>( /) Clear of debris, trees, etc.</li> <li>( ) Some minor debris in channel and a few trees periodicall in channel</li> <li>( ) Much debris in channel and many trees in channel</li> <li>( ) Channel completely blocked by debris and trees</li> <li>Remarks</li></ul>	upber /					•	
<ul> <li>() Some minor debris in channel and a few trees periodicall in channel</li> <li>() Much debris in channel and many trees in channel</li> <li>() Channel completely blocked by debris and trees</li> <li>Remarks</li> </ul> Are there any type of instruments on the dam? <ul> <li>() No</li> <li>() No</li> <li>() Monumentation</li> <li>() Piczometers</li> <li>() Veirs, etc.</li> <li>() Other</li> <li>Explain kevel manometer mather the dam</li> </ul>	()	Close of debris		-			•
<pre>in channel ( ) Much debris in channel and many trees in channel ( ) Channel completely blocked by debris and trees Remarks Are there any type of instruments on the dam? ( ) No ( ) No ( ) Monumentation ( ) Relief wells ( ) Piezometers ( ) Weirs, etc. ( ) Other Explain keel monometer inside the clan </pre>		OTEGT OF GEDITO.	. trees. et	C.			
( ) Much debris in channel and many trees in channel ( ) Channel completely blocked by debris and trees Remarks Are there any type of instruments on the dam? ( ) No ( ) No ( ) No ( ) Monumentation ( ) Relief wells ( ) Piezometers ( ) Weirs, etc. ( ) Other Explain level manometer mether the dam	$\dot{c}$	Some minor debri	, trees, et is in chann	c. el and a f	ew trees	period	ically
( ) Channel completely blocked by debris and trees          Remarks         Are there any type of instruments on the dam?         ( ) No         ( ) Monumentation         ( ) Relief wells         ( ) Piezometers         ( ) Other         Explain         ( ) Other         Explain	<u>ز</u> ز	Some minor debri	, trees, et is in chann	c. el and a f	ew trees	period	ically
Remarks         Are there any type of instruments on the dam?         ( ) No         ( ) Monumentation         ( ) Relief wells         ( ) Piezometers         ( ) Weirs, etc.         ( ) Other         Explain         Water level manometer inside the dam		Some minor debris in channel	, trees, et is in chann channel and	el and a f	ew trees	period:	icall
Remarks Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( ) Piezometers ( ) Weirs, etc. ( ) Other Explain Water level manometer inside the dam		Some minor debris, Some minor debris in channel Much debris in c Chappel complete	, trees, et is in chann channel and	el and a f many tree	ew trees s in char and tree	period:	ically
Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( ) Piezometers ( ) Weirs, etc. ( ) Other Explain Water level manometer inside the dam	() () ()	Some minor debris in channel Much debris in c Channel complete	, trees, et is in chann channel and ely blocked	el and a f many tree by debris	ew trees s in char and tree	period: nnel es	icall
Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( ) Piezometers ( ) Weirs, etc. ( ) Other Explain Water level manometer inside the dam	( ) ( ) ( ) Remar	Some minor debris, in channel Much debris in c Channel complete	, trees, et is in chann channel and ely blocked	el and a f many tree by debris	ew trees s in char and tree	period: nnel es	icall
Are there any type of instruments on the dam? ( ) No ( ) Monumentation ( ) Relief wells ( ) Piczometers ( ) Weirs, etc. ( ) Other Explain Water level manometer inside the dam	( ) ( ) ( ) Remar	Some minor debris, in channel Much debris in c Channel complete	, trees, et is in chann channel and ely blocked	el and a f many tree by debris	ew trees s in chan and tree	period nnel es	icall <sub>:</sub>
Are there any type of instruments on the dam? () No () Monumentation () Relief wells () Piczometers () Weirs, etc. () Other Explain Water level manometer inside the dam	( ) ( ) ( ) Remar	Some minor debris, in channel Much debris in c Channel complete	, trees, et is in chann channel and ely blocked	el and a f many tree by debris	ew trees s in chan and tree	period: nnel es	icall
<ul> <li>() No</li> <li>() Monumentation</li> <li>() Relief wells</li> <li>() Piezometers</li> <li>() Weirs, etc.</li> <li>() Other</li> <li>Explain Water level manometer made the dam</li> </ul>	( ) ( ) ( ) Remar	Some minor debris, in channel Much debris in c Channel complete	, trees, et is in chann channel and ely blocked	el and a f many tree by debris	ew trees s in chan and tree	period: nnel es	icall
<ul> <li>() No</li> <li>Monumentation</li> <li>Relief wells</li> <li>() Piezometers</li> <li>() Weirs, etc.</li> <li>() Other</li> <li>Explain Water level manometer made the dam</li> </ul>	( ) ( ) ( ) Remar	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks	, trees, et is in chann channel and ely blocked	el and a f many tree by debris	ew trees s in chan and tree am?	period: nnel es	icall
<ul> <li>Monumentation</li> <li>Relief wells</li> <li>Piezometers</li> <li>Weirs, etc.</li> <li>Other Explain Water level manometer made the dan</li> </ul>	( ) ( ) ( ) Remar	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks	, trees, et is in chann channel and ely blocked instrument	el and a f many tree by debris s on the d	ew trees s in chan and tree am?	period: nnel es	icall
<ul> <li>() Relief wells</li> <li>() Piczometers</li> <li>() Weirs, etc.</li> <li>() Other Explain Water level manometer made the dan</li> </ul>	( ) ( ) ( ) Remar	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks here any type of No	, trees, et is in chann channel and ely blocked instrument	el and a f many tree by debris s on the d	ew trees s in chan and tree am?	period: nnel es	icall
<ul> <li>() Piezometers</li> <li>() Weirs, etc.</li> <li>() Other Explain Water level manometer marke the dam</li> </ul>	( ) ( ) ( ) Remar	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks here any type of No	, trees, et is in chann channel and ely blocked instrument	el and a f many tree by debris s on the d	ew trees s in chan and tree am?	period: nnel es	icall
<ul> <li>() Weirs, etc.</li> <li>() Other Explain Water level manometer marke the dan</li> </ul>	( ) ( ) ( ) Remar	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks here any type of No Monumentation Palief wells	, trees, et is in chann channel and ely blocked instrument	el and a f many tree by debris s on the d	ew trees s in chan and tree am?	period: nnel es	icall
<ul> <li>() Werrs, etc.</li> <li>() Other Explain Water level manometer marke the dan</li> </ul>	( ) ( ) ( ) Remar	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks here any type of No Monumentation Relief wells Piogemeters	, trees, et is in chann channel and ely blocked instrument	el and a f many tree by debris s on the d	ew trees s in chan and tree am?	period: nnel es	icall
() uther Explain Water level manometer marke the dan	( ) ( ) ( ) Remar	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks here any type of No Monumentation Relief wells Piczometers	, trees, et is in chann channel and ely blocked instrument	el and a f many tree by debris s on the d	ew trees s in chan and tree am?	period: nnel es	icall
Explain Water level manometer matte the dan	( ) ( ) ( ) Remar Are t ( ) ( ) ( ) ( )	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks here any type of No Monumentation Relief wells Piczometers Weirs, etc.	, trees, et is in chann channel and ely blocked instrument	el and a f many tree by debris s on the d	ew trees s in chan and tree am?	period: nnel es	
	( ) ( ) ( ) Remar Are t ( ) ( ) ( ) ( ) ( )	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks	, trees, et is in chann channel and ely blocked instrument	el and a f many tree by debris s on the d	ew trees s in chan and tree am?	period:	icall
	( ) ( ) ( ) Remar Are t ( ) ( ) ( ) ( )	Some minor debris, Some minor debris in channel Much debris in c Channel complete ks here any type of No Monumentation Relief wells Piczometers Weirs, etc. Other Explain	, trees, et is in chann channel and ely blocked instrument	el and a f many tree by debris s on the d	ew trees s in chan and tree am?	period: nnel es	dan

27. If planviews are not available at the time of the inspection, sketches and typical cross sections should be made on the back of these sheets to name and locate principal components of the dam.

which deserve special consideration in regard to safety of the structure? (summarize from input on forms a thru g) Investight The state of the states interesting incomparises 1. 2. 3. 4. • 5. 6. and the second 7. 8. -9. 10. 11. 12.

#### Participants in the dam inspection:

Name	Title	Agency
David Zuellet	Team leader Strating	Barr Engliseering Co.
Charles Relin	Geotechnical	Rart Engineering Co.
Lama Zeug	Highstran Audraulics	Batt Engineering Co.
l		l
••••••••••••••••••••••••••••••••••••••		
		and the second

28. Based on the visual inspection of the dam, are there any areas

# List of attached forms

Inventory Form ) ( U.S.G.S or County Map ) Form A Embankment Dam ( / ) Spillway Form B ( ) ) Form C Conduit ( Form D Concrete Masonry or Timber Gravity Dam ) ( Powerhouse ·Form E ( ) Form F Concrete Condition ( ) Form G Site Geology  $( \land )$ Other ( ) List:

#### FORM A - EMBANKMENT DAM

(If plans are available item no. 1 need not be completed.)

1. On a separate sheet, draw one or more sections through the dam. Show crest, width, height, slopes, major type(s) of materials, foundation treatment, provisions for internal drainage (if any), location of outlets, slope protection, upstream and downstream water surface, high water marks, eroded or damaged areas, seepage, etc. Describe features not adequately shown on sketch.

Beland This section while performs to the encounterment I are projet about and the doon the loc est received the mass concrete gravity down som meller celling tool is backaded will set the right ale no soillage.

2. Based on the exposed material in the downstream channel and any other physical evidence. Describe the foundation and embankment material.

Bedrick Bundaling, Ficher and Ell. Represe on mostron.

3. Basis for foundation and embankment description.

side

- (1) Borings
- ( J Construction records
- ( ) Verbal testimony
- ( J Visual observation
- ( ) Waterwell records
- ( ) Other explain

A-1

Are there any signs of instability? ( ) Cracks ( ) Sloughing ( ) Irregularities in crest or waterline ( ) Excessively steep slopes ( ) History of sliding ( ) Other Remarks <u>The Conbankersule three slope of the stability of the dam.</u> <u>head to be called of the dam.</u> Give your opinion of the stability of the dam. ( ) Embankment has no visible stability problems a	<u>stypess</u> <u>stores</u>
Are there any signs of instability? ( ) Cracks ( ) Sloughing ( ) Irregularities in crest or waterline ( ) Excessively steep slopes ( ) History of sliding ( ) Other Remarks <u>pc Conbackmente hue elequente</u> <u>but the thek core will doe and male them</u> <u>hund to the calify of theda</u> <u>Minipu could</u> ofted Give your opinion of the stability of the dam. ( ) Embankment has no visible stability problems a	<u>stypess</u> <u>stypess</u> <u>storestans</u>
Are there any signs of instability? ( ) Cracks ( ) Sloughing ( ) Irregularities in crest or waterline ( ) Excessively steep slopes ( ) History of sliding ( ) Other Remarks <u>The Conbackmante have sloped</u> <u>but the thet core will does not make the theory of the thete core will does not the theory of the thete the thete core the thete and the thete core thete thete thete and the thete core thete thete</u>	<u>stypess</u> <u>stypess</u> <u>stores</u> <u>stores</u>
Are there any signs of instability? ( ) Cracks ( ) Sloughing ( ) Irregularities in crest or waterline ( ) Excessively steep slopes ( ) History of sliding ( ) Other Remarks <u>The Conbankmanic bive sleep classical</u> and the thick core will does all made the <u>has d to be called of the day of the day</u> . ( ) Embankment has no visible stability problems a	<u>stypess</u> <u>s de a staas</u> <u>1 or - taast</u>
<ul> <li>( ) Cracks</li> <li>( ) Sloughing</li> <li>( ) Irregularities in crest or waterline</li> <li>( ) Excessively steep slopes</li> <li>( ) History of sliding</li> <li>( ) Other</li> <li>Remarks <u>De Cobackmanic bing sloped</u></li> <li>bit <u>the thek core will does det main data to the cally of the data.</u></li> <li><u>insert to the cally of the data.</u></li> <li>Give your opinion of the stability of the dam.</li> <li>( ) Embankment has no visible stability problems a</li> </ul>	<u>stypesy</u> <u>s DE a stans</u> <u>a ga stans</u>
<ul> <li>( ) Sloughing</li> <li>( ) Irregularities in crest or waterline</li> <li>( ) Excessively steep slopes</li> <li>( ) History of sliding</li> <li>( ) Other</li> <li>Remarks <u>The Conbankmanic time sloop and the time core will does not make does not d</u></li></ul>	<u>stypesy</u> <u>s De a stans</u> <u>a ge stans</u>
<ul> <li>( ) Irregularities in crest or waterline</li> <li>( ) Excessively steep slopes</li> <li>( ) History of sliding</li> <li>( ) Other</li> <li>Remarks <u>The embandment has a feature of mole days</u></li> <li><u>but the thek core will does not mole days</u></li> <li><u>but to the calely of ineda</u> <u>discondent</u></li> <li><u>but to the calely of ineda</u> <u>discondent</u></li> <li><u>but to the calely of ineda</u> <u>discondent</u></li> <li><u>but to the calely of ineda</u></li> <li><u>calely of the dam</u>.</li> <li>( ) Embankment has no visible stability problems a</li> </ul>	<u>stypess</u> <u>o de stans</u> 1 or Junad
<ul> <li>() History of sliding</li> <li>() History of sliding</li> <li>() Other</li> <li>Remarks <u>De Conbankranke hue sleep etc</u></li> <li><u>but the thek core will does not mole them</u></li> <li><u>but to tre calely of iteds</u>. <u>Missipa could</u></li> <li><u>but to tre calely of iteds</u>. <u>Missipa could</u></li> <li>Give your opinion of the stability of the dam.</li> <li>() Embankment has no visible stability problems a</li> </ul>	<u>stypesy</u> <u>s Dé la stans</u> <u>1 on stanstra</u>
<ul> <li>(1) Other</li> <li>Remarks <u>The Embandence have steeped</u></li> <li>but the thete core will does not male the thete core will does not male the the core will does not male the product to the core of the day.</li> <li>(1) Embankment has no visible stability problems and the product of the stability problems and the stability problems and</li></ul>	<u>stracsa</u> <u>o ot a stars</u> <u>o ot a stars</u>
Remarks <u>pe embandence the stopped</u> but the thete core will does not make the <u>hand to the calledor ineda</u> . <u>Assume coult</u> ofted Give your opinion of the stability of the dam. ( ) Embankment has no visible stability problems a	<u>stypesy</u> <u>s de la stans</u> <u>a or stanstra</u>
Remarks <u>The Embandence time steep als</u> but the thick core will does not note the <u>hand to be called a line to the call</u> oted Give your opinion of the stability of the dam. ( ) Embankment has no visible stability problems a	<u>stypesy</u> <u>s de la stans</u> <u>he danstig</u>
but the thick core will does not make the house d to the cally of the day. As an court of d Give your opinion of the stability of the dam. ( ) Embankment has no visible stability problems a	s DE a stras
how do the cally of theda . As my court ofed Give your opinion of the stability of the dam. ( ) Embankment has no visible stability problems a	to or Assadi
Give your opinion of the stability of the dam.	<u>1. It Annar (</u>
Give your opinion of the stability of the dam. ( ) Embankment has no visible stability problems a	
Give your opinion of the stability of the dam. ( ) Embankment has no visible stability problems a	$\mathcal{L}_{\mathcal{L}} = \{\mathcal{L}_{\mathcal{L}}, \mathcal{L}_{\mathcal{L}}\}$
( ) Embankment has no visible stability problems a	
( ) Embankment has no visible stability problems :	
aritaria cat farth in the avidalines	and may meet
Enterna set forth in the guidelines	out probably doe
not meet the criteria set forth in the guidely	ines
( ) Embankment has minor stability problems but u	nlikely to lead
to failure	
( ) Embankment has stability problems which if not	t corrected
() Embankment has serious stability problems whi	the could lead
to failure at any time	ch could read
( ) Other	
Explain	
. Is there any evidence of seepage?	
Ves No e N/A Canit Tell	
() () () () Down	
	stream slope
$() ( \checkmark () ) ( ) Downs$	stream slope stream of dam
() (U) () (Down: U) (U) (U) (U) (U) (U) (U) (U) (U) (U)	stream slope stream of dam abutment
() (J) (J) () Down() (J) () () Left(loc	stream slope stream of dam abutment oking downstream
$ \begin{array}{c} ( ) & ( ) & ( ) & ( ) & Down \\ ( ) & ( ) & ( ) & ( ) & Left \\ ( ) & ( ) & ( ) & ( ) & Righ \\ \end{array} $	stream slope stream of dam abutment oking downstream t abutment
$ \begin{array}{c} ( ) & ( ) & ( ) & ( ) & Down \\ ( ) & ( ) & ( ) & ( ) & Left \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & Right \\ ( ) & ( ) & ( ) & Right \\ ( ) & Right \\ ( ) & ( ) & Right \\ ( $	stream slope stream of dam abutment oking downstream t abutment oking downstream

-

A-2

Explain fully (quantity, turbidity, location, point source or general area, etc.)

7. Give your opinion of seriousness of seepage based on visual observations.

. (  $\mathscr{N}$  Unlikely that it will become a problem in the foreseeable future

( ) May or may not become a problem

( ) Is a problem but not likely to lead to failure

( ) Is presently a problem which if not corrected could lead to failure

( ) Serious problem which could lead to failure at any time

Remarks \_\_\_\_\_

8. Are there any toe drains or relief wells?  $N_{O}$ 

Are they functioning?

Quantity of observed flow? Slight ( ) Moderate ( ) Heavy ( )

• Not observalbe ( )

9. Is there any slope protection on the embankment? Yes (~) No ( ) (describe) <u>here an undercom slope</u>

10. Is there any evidence of erosion of embankment material?

Yes	No	N/A	Can't Tell	
(5)	()	()		Upstream slope
(X)	()	()	()	Downstream slope
( )	(1)	()	()	Crest
()	(1)	()	( )	Around structures

A-3

10. (Cont'd)

Yes       No       N/A       Can't Tell         ( )       ( )       ( )       Right abutment (looking downstream)         ( )       ( -)       ( )       Left abutment (looking downstream)         ( )       ( )       ( )       Deft abutment (looking downstream)         ( )       ( )       ( )       Others         Remarks
11. Describe material being eroded - estimate uniform soil classification
511-512
<ul> <li>12. Give your opinion of the seriousness of the erosion based on visual observations.</li> <li>( ✓ Unlikely that it will become a problem in the foreseeable future</li> <li>( ) May or may not become a problem</li> <li>( ) Is a problem but not likely to lead to failure</li> <li>( ) Is a problem which if not corrected could lead to failure</li> <li>( ) Is a problem which could lead to failure at any time</li> </ul>
13. Is there any evidence to indicate that the embankment has ever been overtopped? Yes ( ) No ( // (Explain)
14. General condition of dam - maintenance, mowing, trees in embank- ment, animal burrows, etc.
Many trees and on the embruicement, to hours,
to read burrenes asted, good grees could an arest
and downstream druc. Reprop is instream slope
is heavily aroun over with frees.

ŕ

#### 15. Summary

Based on your field observations list the items which you feel may represent a potential hazard to the embankment.



Signature(s) of Person(s) completing this report

all quella.

÷.

A-5

#### FORM D - CONCRETE, MASONRY, OR TIMBER GRAVITY DAM

1. (If plans are available the following need not be completed.) On a separate sheet, draw one or more sections through the dam. Show crest width, height, major types of foundation, water surface upstream and downstream and any pertinent features. On a plan or elevation, show location by dimension of outlets and other features. Describe features not adequately shown on sketch. Identify foundation treatment measures taken.

2. Based on the exposed material in the downstream channel and any other physical evidence, describe the foundation material.

sundation material is sandstone bedrock

3. Basis for foundation description

( S Borings

( ) Construction records

( ) Verbal testimony

( S Visual observation

( ) Waterwell records

( ) Other - Explain

D-1

3. (Cont'd)

4. Are there any signs of instability (i.e. sliding, overturning, bearing)?  $( \land )$ No signs of instability observed Cracks in the concrete, other than temperature or deterioration cracks Displacement at joints ( ) Evidence of movement History of sliding or tipping ) ) Other Remarks: 5. Give your opinion of the stability of the dam based on the observations from question 4.  $\langle \mathcal{N} \rangle$ Structure has no visible stability problems and may meet criteria set forth in the guidelines ( ) Structure has no visible stability problems but probably does not meet the criteria set forth in the guidelines Structure has minor stability problems but unlikely to lead ( ) to failure ) Structure has stability problems which if not corrected could lead to failure Structure has serious stability problems which could lead to ( ) failure at anytime ()Other Explain \_\_\_\_

6. For concrete structures Form F (Surface Condition of Concrete) should be completed. Are there any items listed on Form F which may be caused by overstress of structural members rather than concrete deterioration? 6. (Cont'd)

) No N/A

🗸) No

) Cracks due to overstress in bending on tension

( ) Cracks due to shear or bearing

) Spalls or other deterioration due to overstress

( ) Large deflections

General Locations

7. Give your opinion of the ability of the structural components to carry the applied loads using modern design criteria.

 Structure has no visible structural strength problems and may meet criteria set forth in the guidelines

( ) Structure has no visible structural strength problems but probably does not meet the criteria set forth in the guidelines

( ) Structure has minor structural strength problems but unlikely to lead to failure

() Structure has structural strength problems which if not corrected could lead to failure

) Structure has serious structural strength problems which could lead to failure at anytime

) Other Explain

8. Are there any loads on the structure which may not have been included in the original design but could be causing overstress in some structural components?

( ) None observed

( ) Large silt deposits on upstream face

) Increased load due to heavier traffic

) Additional or larger equipment loads (cranes, generators, dead load)

Remarks:

Ć

9. Are there any drains or weepholes which appear to be functioning improperly? .

- $(\checkmark)$  No drains or weepholes noted
- ) Generally yes
- ( ) Generally no
  - ) Can't tell

10. Is there evidence of seepage? (Seepage at embankment tie-ins should be covered in section on embankment dams.)

Yes	No	N/A	Can't Tell	
( 🖒	(`)	()	( )	Downstream of dam
(~) /	()	()		Left abutment (looking downstream)
<b>(</b> ~ <sup>1</sup> <b>)</b>	( )	()	( )	Right abutment (looking downstream)
()	( )	()	(~)	Through structure
()	()	( 🗳 👘	( )	Other (relief drains)

Explain fully (quality, turbidity, location, point source of general area, etc.) and/or locate evidence of seepage on a profile and plan sketch.

Water is clear and quantity to small to be

11. Give your opinion of the seriousness of the seepage based on field observations.

- ( ) No seepage noted
- ( ) Unlikely that it will become a problem in the foreseeable, future
- May or may not become a problem
- ( ) Is a problem but not likely to lead to failure

 Is presently a problem which if not corrected could lead to failure

- ) Serious problem which could lead to failure at anytime
- ( ) Other Remarks:

(

12. If gravity dam is not designed as an overflow structure do not complete items 12 through 24.

Check the type of spillway section(s) included in the gravity section

- ( ) Ungated fixed crest
  - ) Fixed crest with flash boards
- Tainter gate (
  - ) Stoplog
  - Roller gate
- ) Other

Describe

13. Give your opinion of condition of gates

( /) N/A. No gates Gates appear to be in good condition and unlikely to cause problems in the foreseeable future Gates have some problems not likely to impair operation ( ) Gates have some problems which could lead to failure during an emergency Gates are in such poor condition that failure could occur ) at anytime

• • •

Remarks:

14. Give your opinion of condition of stop logs or flash boards  $(\sqrt{)}$  N/A. No stop logs or flash boards Stop logs/flash boards appear to be in good condition ) Stop logs/flash boards have some problem areas but are not likely to impair operation Stop logs/flash boards have serious problems which could ( ) cause operation problems Describe how flash boards are controlled and what head controls 15. them ( / N/A. No flash board ( ) Description

16. Where are stop logs kept when not in use?

17. Did you attempt to operate the gates?

( ) N/A. No gates
( ) Yes, successfully
( ) Yes, unsuccessfully
( ) Yes, partial success
( ) No, couldn't get permission
( ) No, necessary equipment not available
( ) No, obviously inoperable
( ) No, but owner indicates that they are operable

Remarks:

18. Are spillway gates normally

( ) N/A. No gates
( ) Open
( ) Closed
( ) Other Explain

19. In your opinion, what problems would failure of the gates to open cause?

N/A. No gates
Little or none
Would make drawing down the lake difficult
Would partially reduce the ability to safely pass a flood
Would drastically reduce the ability to safely pass a flood
Other

20. In your opinion, what problems would a failure of the gates that permitted uncontrolled release of water cause?

21. Is there any evidence of erosion or deterioration of the spillway portion of the dam?

Yes	No ( )	N/A ( )	Can't Tell ( )	Spillway floor
()	()	()	()	Spillway side slopes
<b>(</b>			( )	Around control sill or over- flow ogee
( )	( )	(5	( )	Around spillway gates or control structure
			· · ·	

22. Give your opinion of the seriousness of the erosion of the spillway portion of the dam.

( ) Unlikely that it will become a problem in the foreseeable future

) May or may not become a problem

(  $\checkmark$ ) Is a problem but not likely to lead to failure

) Is a problem which if not corrected could lead to failure

( ) Is a serious problem which could lead to failure at anytime

( ) N/A

23. Is there any evidence of erosion upstream or downstream of the spillway?

()	Visual evidence	U.S.	D.S.
$( \land )$	Sounding data	U.S.	🗸 D.S.
()	Flow pattern	U.S.	D.S.
()	Operators observation	U.S.	D.S.
()	Other evidence	· ·	

D-7

24. Is there any evidence of undermining of the structure due to erosion?

	<ul> <li>( ) No</li> <li>( ) Yes, see attached sketch or ma</li> <li>( ) Yes, describe location(s) and</li> </ul>	.p amount(s) of erosion
25.	Is there an upstream or downstream r	iprap apron? N⊃
	<ul><li>a. Is it visible? U.S D</li><li>b. What is its condition?</li></ul>	·····
	<ul> <li>( ) Intact</li> <li>( ) Ends undermined or eroded</li> <li>( ) Rock displaced or missing</li> </ul>	

26. Give your opinion of the seriousness of the erosion.

No erosion noted ( ) (

) Unlikely that it will become a problem in the foreseeable future

 $(\checkmark)$ May or may not become a problem

Is a problem but not likely to lead to failure )

Is a problem which if not corrected could lead to failure )

Is a serious problem which could lead to failure at anytime · ) ( )

Other Remarks:

(

(

(

27. Based on field observations list items believed to represent significant potential hazards to the integrity of the dam.

(1)	None noted			 		•
(2)		· · · · ·		 · 		
(3)			•		······································	
(4)	······			 		
27. (Cont'd) (5) (6) • (7) (8) (9) \_\_\_\_\_

Signature(s) of Person(s) completing this section

ion MI - Sector 25 Julice

### FORM E - POWERHOUSE

## 1. Does the Powerhouse function as part of the dam and retain water?

( YYes ( ) No. Separate Powerhouse

2. Is the power generation equipment still in place and functioning?

( ) Not in place ( ) In place, not functioning ( / In place and functioning

3. Are there any signs of instability (i.e. sliding, overturning, bearing)?

- No signs of instability observed
- Cracks in the concrete, other than temperature or deterioration cracks
- Displacement at joints
- Evidence of movement
- History of sliding or tipping

Other

Remarks: Crocks in The arches of the privetheres.

ween noted

Antore of craches is unkillionian. Cracks have been For set 45 years with no walltonal observed movement. 4. Give your opinion of the stability of the powerhouse based on the observations from question 3.

- Structure has no visible stability problems and may meet ()criteria set forth in the guidelines
- Structure has no visible stability problems but probably ( ) does not meet the criteria set forth in the guidelines
- Structure has minor stability problems but unlikely to lead ()to failure
- Structure has serious stability problems which could lead ()to failure at any time
  - Other Explain

E-1

E NOTTENDO 2005

5. For concrete structures form F (surface condition of concrete) should be completed. Are there any items listed on form F which maybe caused by overstress of structural members rather than concrete deterioration?

( 🗳 No signs of overstress noted

- ( ) Cracks due to overstress in bending or tension
- ( ) Cracks due to shear or bearing
- ( ) Spalls or other deterioration due to overstress
- ( ) Large deflections

General Location:

6. Are there any loads on the structure which may not have been included in the original design but could be causing overstress in some structural components?

- ( ) None observed
- ) Large silt deposits on upstream face
- ( ) Increased load due to heavier traffic
- Additional or larger equipment loads (cranes, generators, dead load)

Remarks:

7. Give your opinion of the ability of the structural components to carry the applied loads using modern design criteria.

- ( ) Structure has no visible structural strength problems and , may meet criteria set forth in the guidelines
- ( ) Structure has minor structural strength problems but unlikely to lead to failure
- Structure has structural strength problems which if not corrected could lead to failure
- ( ) Structure has serious structural strength problems which could lead to failure at any time
- () Other
  - Explain

8. Are there any drains or weepholes which appear to be functioning improperly?

( ) No drains or weepholes noted
( ) Generally yes
( ) Generally no
( ) Can't tell

9. Is there evidence of seepage?

(Seepage at embankment tie-ins should be covered in section on embankment dams)

Yes	No	» N/A	Can't Tell	
( )	()	()	()	Downstream of powerhouse
( )	()	()	()	Left side (looking downstream)
(*)*	()	()	(~)	Right side (looking downstream)
()	()	· ( )	()	Through structure
()	()		( )	Other (relief drains)

Explain fully (quality, turbidity, location, point source of general area etc.) and/or locate evidence of seepage on a profile and plan sketch.

siter exiting at joint with belode suteropping errap 05-01 trade to Side at construction joints.

10. Give your opinion of the seriousness of the seepage based on field observations.

( ) No seepage noted.
( ) Unlikely that it will become a problem in the foreseeable future
( ) May or may not become a problem
( ) Is a problem but not likely to lead to failure
( ) Is presently a problem which if not corrected could lead to failure
( ) Serious problem which could lead to failure at any time
( ) Other

-		
11.	Туре	of powerhouse gates
		N/A gates removed openings permanently sealed.
	( )	Slide gates
	$\left( \right)$	Stop logs
	()	Tainter gate
	()	Other
		n an
	<b></b>	
		· · · · · · · · · · · · · · · · · · ·
•	·	
12.	Did v	on attempt to operate the gates?
	]	
	$( \cdot )$	N/A. No gates
	$\tilde{c}$	Yes successfully
	23	Yes unsuccessfully
		Yes partial success
		No ocultat success
	$\left( \begin{array}{c} \cdot \\ \cdot \end{array} \right)$	No, courde t get permission
		No necessary equipment not available
		No, ovblously inoperable
		No, but owner indicates that they are operable.
13.	Are s	pillway gates normally
	()	N/A No gates
	( )	
		olegod
		closed
	• • • • •	· · · · · · · · · · · · · · · · · · ·
•	•	
14.	Give	your opinion of condition of gates.
	()	N/A. No gates
	25	Gates appear to be in good condition and unlikely to cause probl
	· · /	in the forseeable future
	( )	Cates have come problems not likely to impoir operation
		Cates have some problems not inkery to impair operation
	()	bales have some problems which could lead to failure during an
	2 5	emergency
	()	Gates are in such poor condition that failure could occure at
		any time
	•	

Ę.

14. Give your opinion of condition of gates.

(

C (

(

(

	(	)	N/A. No gates
	(	)	Gates appear to be in good condition and unlikely to cause
			problems in the forseeable future
	(	)	Gates have some problems not likely to impair operation
	(	)	Gates have some problems which could lead to failure during
			an emergency
	(	)	Gates are in such poor condition that failure could occur
			at any time
Rema	arks	:	
		*****	

In your opinion, what problems would failure of the gates to open -15. cause?

) N/A. No gates  $( \land )$ Little or none Would make drawing down the lake difficult ) Would partially reduce the ability to safely pass a flood ) ) Would drastically reduce the ability to safely pass a flood Other )

16. In your opinion, what problems would a failure of the gates that permitted uncontrolled release of water cause?

N/A. No gates ( ) ( ) Little or none ( ) Would drain lake, but no safety problems C ) May cause serious erosion of dam ( Could release enough water to be a flood hazard ) ( Other )

E--5

17. Is there any evidence of erosion upstream or downstream of the powerhouse?

( ) Visual evidence U.S. D.S.
( ) Sounding data U.S. D.S.
( ) Flow Pattern U.S. D.S
( ) Operators Observation U.S. D.S. ( ) Other evidence 18. What is the condition of riprap  $(\checkmark)$  No riprap ( ) Badly displaced () Occasional holes and pockets () Rock deteriorated 19. Are there any obstruction to flow through the powerhouse? (V) No () Yes Describe flow pattern: . . . . . . . . . . . 20. In your opinion would an abnormally large powerhouse discharge have a tendency to erode the embankment? ( ) No ( ) Yes Describe <u>Fundence</u> of repuir work to rock alteropping doinstream à privertieuse

E-6

 (1)
 Crudence if the areles in the backtore

 (2)
 (3)

 (4)
 (5)

 (6)
 (6)

21. Based on your visual observations list any conditions which you believe may have a potential affect on the integrity of the dam.

Signature(s) of person(s) completing this section

M. Zerry la ration Relin 

# FORM F - SURFACE CONDITION OF CONCRETE (From ACI Report 65-67)

1. Identify the feature for which this section applies. Spillion and proviniuse 2. General condition of concrete ( ) Good
( ) Satisfactory
( ) Poor Remarks: Right half of spillway, boking constraining, is severally ended. Spalling on left abouttment of returning dam. 3. Cracks ( ) No Describe Cracks in the arches of the powerhouse. Direction Maximum Width ( ) fine (less than 1 mm or 3/64") ) Longitudinal ( ) Transfers ( ) Vertical ( ) medium (1 mm to 2 mm or 3/64" to 5/64") ( / wide (more than 2 mm or more ) Diagonal ) Random than 5/64") Mineralization None Туре ( ) Leaching
( ) Stalactites
( ) Stalagmites ) Pattern cracking ) Checking) Hariline cracking D-cracking Scaling () Yes () No 4. Describe

l cm or l clearly exp loss of C.A	3/64" to 25/ osed and sta .)	64", C.A. e nds out)	xposed)
clearly exp loss of C.A ( ) No	osed and sta .)	nds out)	
( 🔿 No			
( ⁄ ) No			·. •
			_
		•	
	· · · · · · · · · · · · · · · · · · ·		
		•	
······································		•	
	······		
		••	•
ST lett	abutturent	on down	stream
dam.	Minor Sp	alling on	TIONE
<u></u>	· · · · · · · · · · · · · · · · · · ·		
١			•
han 2 cm de	ep and 15 cr	a long or 3/	4" deep a
	•		
•			
			· · ·
		· ·	
			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	han 1 cm di 5 cm diamet han 5 cm di ( ) No 57 left dam.	han 1 cm diameter or 25 5 cm diameter or 25/64" han 5 cm diameter or 2" ( ) No of left abuttment clam. Minor sp may? han 2 cm deep and 15 cm	han 1 cm diameter or 25/64" diamet 5 cm diameter or 25/64" to 2" diam han 5 cm diameter or 2" diameter) () No <u>ST left abouttment on down</u> <u>clain. Minor spalling on</u> <u>stan</u> . han 2 cm deep and 15 cm long or 3/

() Chemical attach

7. (Cont'd)

Describe All many left and some . In your opinion, what is the effect of the condition of the concrete 8. on the safety of the dam? ) Little or none ( ) Aesthetic problems but nothing that would effect the integrity of the structure. ) May create operational problems, but no safety problem ) If uncorrected, could eventually become a safety problem It is a safety problem that could result in a large uncon-) trolled release of water Other ( ) Explain \_\_\_\_\_

Signature(s) of person(s) completing this section

ion M. Jean 7 relle

F-3

## FORM G - GEOLOGY

The items in this report are divided into two general categories:

- a. Description of the General Geology of the basin (items 1 through 14)
- b. Description of site geology (items 15 through 21)

GENERAL GEOLOGY OF THE BASIN

- 1. Glacial ( ⁄) Non-glacial ( )
- 2. Glacial
  - (v) Till plain
  - ( ) End moraine
  - ( ) Outwash plain
  - ( ) Combination Explain
- 3. River Valley
  - ( ) Deeply incised
    ( ) Shallow
  - () Broad
  - (/) Steep sided
- ( ) Terraced( ) Meandering

Non-Glacial

( ) Meandering ( ) Other - Explain

) Deeply disected

() Rather level

- 4. Topography
  - ( ) Level or even
  - ) Rolling
  - ( /) Hilly
    - ) Knob & kettle
    - ) Other Explain \_
- 5. Empoundment

(

- () Lake
  - ) River
- ( /) Combination Explain \_\_\_\_\_

6.	Soils		•	
	<u>Origin</u>	Ty	pes	
	<ul> <li>Outwash</li> <li>Loess</li> <li>Boulder Clay</li> <li>Alluvial</li> <li>Marsh</li> <li>Glaciofluvial</li> </ul>	() () () () () () () () () () () () () (	Sand-gravels Clays Silts Organic Other Explain	
	Explain	•		
		1. A.		•
7.	Effect of Topography on Drainage		•	
	() Even () Slow			
8.	Effect of Soil Type on Drainage ( V) Rapid ( ) Even	•		
	( ) Slow	•		
9.	Bedrock Geology of Basin			
	Formation Name Pravice Du Chi	<u>2n (</u>	proup	•
•	Rock Type Small Dolo	mite		
	General Depth to Rock $0-2^{1}$			· · · · · · · · · · · · · · · · · · ·
	Outcrops in Valley Walls		-	
10.	Source of Bedrock Information ( ) Visual ( ) Well records ( ) Borings	· · · · · · · · · · · · · · · · · · ·		

(

# 11. General Water Table

Source of water to stream flow

- (  $\bigcirc$  ) Surface runoff
- ( ) Lakes, marshes
- () Springs
- ( ) Ground water
- ( ) Slumping or slides in reservoir
  ( ) Slumping or slides in downstream channel 12.
- ( ) Sink holes or surface depression 13.
- 14. ( /) Groundwater discharge area
  ( ) Groundwater recharge area

## SITE GEOLOGY

# 15. Geologic Setting

- () Glacial
  - ) Outwash plain
  - ( ) Till plain( ) End moraine
- ( ) Non-glacial () Deeply disected plain ( ) Alluvial plain
- () <u>Terraces</u> ) Soil ) Rock
- 16. Bedrock

Formation Names: Provice Do Chien Group (/) Exposed ( ) Deeply buried
( ) Sandstone ( ) Limestone Dolmite ) Shale ) Igneous ( ) Balsalt ) Granite ( ) Other - Explain

#### Abutments and Foundation 17.

- () Soil Types 🚲
- (~) Rock Types
- 18. Seepage

Nore ( ). Pervious soils

- ( ) Bedding planes or joints in rock
- ( ) Fracture zones in rock

#### 19. Rock Structure

- a. Bedding
  - () Horizontal
  - ) Dipping (
  - ( ) Massive bedded
  - ) Medium bedded (
  - Thin bedded ( )
- Ъ. Bedding Planes
  - ( )) Open
  - () Closed
- c. Joints
  - () Close spaced
  - ( ⁄) Widely spaced
  - ( ) Direction and inclination to structure

( ) N/A - Explain \_\_\_\_\_

# d. Bedding Planes

2 Open 610sed

- e. Hardness of Rock
  - (V) Soft
  - (/) Medium
  - () Hard
- Cementation f.
  - ( / Well cemented
    - ) Poorly cemented

1

) Non-cemented (

G-4

20. On a separate sheet of paper draw an approximate geologic profile along the centerline of structure showing assumed or known soil and rock profile in the abutment and foundation areas. Identify major soil types or rock formations.

21. Based on visual observations made at the site list the geologic conditions which are believed to represent major potential threats to the safety of the dam.



Signature(s) of Person(s) completing this section

on. U.

STATE SEG RIV ID. NO. DIV	PRIMARY SECONDARY P REPORT
HN 00438 NCD	HN 157 01 J, SIBLEY 4413.5 9231.5 01JUN73
	POPULAR NAMENAME OF IMPOUNDMENT
•	REG BARIVER OR STREAMNEAREST DS CITY DIST POPULATION
	07 05 TR-ZUMBRO ZUMBRO FALLS 7 164
	TYPE OF DAM YR-COM -PURPOSES- S-HGT M-HGT MAX-STR NOR-STR
•	RE 1958 C 29 27 20 3
	REMARX3REMARXSREMARKSREMARXS
	STR-20 109 14 FS-3.C.S.
· · ·	H CREST T MOTH DISCH VOLUMEPOWER I/PNAVIGATION LOCKS
	RICHARD SIBLEY USDA SCS USDA SCS
	USDA SCS USDA SCS DUD DIN OF WITTER AND OF WITTER AND OF WITTER
	CSCA SCS CSUA SLS CARE-DIA OF WATERS CAN-DIA OF WATERS
· · ·	INSPECTION BY INSP DATEAUTHORITY FOR INSPECTION
• • • • • • • • • • • • • • • • • • •	NONE
•	REHARKSREHARKSREHARKSREHARKSREHARKSREHARKSREHARKS
STATE SEG RIV ID. NO. DIV	PRIMARY SECONDARY REPORT
HN 00358 NCD	MN 157 01 ZUHBRO LAKE 4412.8 9228.7 16JAN70 -
	NAME OF IMPOUNDMENT
a de la companya de l La companya de la comp	ZUHBRO LAKE
	67 05 ZUMBRO RIVER ZUMBRO FALLS 10 198
	TYPE OF DAM TR-CON -PURPOSES- S-MGT M-HGT MAX-STR NDR-STR
•	76 60 21000 12300
•	REMARKSREMARKSREMARKS
	\$P-51+5211_VIED 12-BAFFEITA 50'WYXEV 218-51 704 14
	H CREST T HOTH DISCH VOLUMEPOWER I/PNAVIGATION LOCKS
	1 U 440 50000 Z.3 Z.3
•	
• •	CITY OF ROCHESTER HUGH L. CCOPER AND CO. CITY OF ROCHESTER
	DESIGNCONSTRUCTIONOPERATIONMAINTENINCE
	NONE ONR-DIV OF WATERS DWR-DIV OF WATERS
. •	INSPECTION BY INSP DATE
•	Barr Engr. Co. 22 May 79 PL92-367
	REMARX3REMARXSREMARXSREMARXSREMARXSREMARXS

32, 33, 34 ESTINATED

303

APPENDIX B

HYDRAULIC AND HYDROLOGIC CHECKLIST

Sheet 1	$\mathbf{of}$	
Date		
[D		
Sector Se		and the second sec

# NATIONAL DAM SAFETY PROGRAM

# HYDROLOGY AND HYDRAULICS STUDY CHECK LIST

ver Za	volere River Nearest Downstream Town Zahnere Falls	
General 1	Data	
	Drainage area <u>661</u> sq. mi.	•
	Total length of longest watercourse (L) miles*	
	Fall of basin from the farthest point to the dam $H = 55$ fe	eet:
•	Average slope of the basin convert feet/feet*	
	Average stope of the basin 0.00107 feet/feet.	•
	Time of concentration (t <sub>c</sub> ) hours*	-
	Type of cover (develop by approximate estimate, not	•
	Type of cover (develop by approximate estimate, not precise computation)	•
	Type of cover (develop by approximate estimate, not precise computation) Urban%	
	Type of cover (develop by approximate estimate, not precise computation) Urban % Forest %	
	Type of cover (develop by approximate estimate, not precise computation) Urban % Forest % Grassland %	
	Type of cover (develop by approximate estimate, not precise computation) Urban % Forest % Grassland % Crop 72 %	
	Type of cover (develop by approximate estimate, not precise computation) Urban % Forest % Grassland % Crop 72 % Lake and swamps 0 %	
	Type of cover (develop by approximate estimate, not precise computation) Urban% Forest% Grassland% Crop72% Lake and swamps% Other%	
	Type of cover (develop by approximate estimate, not precise computation) Urban % Forest % Grassland % Crop 72 % Lake and swamps % Other 0 % Explain	
	Type of cover (develop by approximate estimate, not precise computation) Urban Forest Grassland Crop 72 % Lake and swamps 0 % Other 0 % Explain Total 100 %	

\* See page 14-7 of Chows, "Handbook of Hydrology" for definition.

Sheet 2 of \_\_\_\_\_ Date \_\_\_\_\_ ID \_\_\_\_\_

	Current spillway design flood: Yes No Peak Quality cfs
•	Current spillway design flood hydrograph: Yes / No Incl#
	Other pertinent data: Montes Probable Mose generated and routed
	Downstream Channel X - Sections: Yes No Incl#
	Rough sketches of cross-section downstream of dam showing distance below the dam, channel and overbank dimensions, n values, and slope.
900 3	Et is Right Issting aprivement. Chanter longth, 1850' connectream from dans
- 380 -	n=0.10
- 078 -	0:0.03 5
HZH 360 -	
Elevat	Slope = 0.00297 $f_{f_{t}}$
850 -	
540 .	$\frac{1}{200}$

Station, Feet

Sheet	3	of		
Date	_		-	•
ID				

2. Channel capacity in critical downstream reach <u>compare</u> cfs.

3. Flood Plain Development

First 1000 feet downstream Privitely owned campyioninds Between 1000 feet and 1 mile Agriculture and light residential Between 1 mile and 5 miles Agriculture and light residential development Other critical reach

4. Description of outlet works, including stilling basin. Give plan, profile, cross-section sketches with important elevations, dimensions, and water surfaces. Plans available: Yes <u>No</u> Incl#\_\_\_\_\_

_		cfs	% frequency
Capacity:	with $\underline{2}$ ft. of freeboard		
	without freeboard		
	normal operating capacity at <u>925</u> elevation	·600	44

5. Description of service spillway, including stilling basin. Give plan, profile, cross-section sketches with important elevations, dimensions, and water surfaces. Plans available: Yes <u>No</u> Incl#

Capacity:	with ft. of freeboard	<u>cfs</u>	% frequency
	without freeboard		
	normal operating capacity at <u>925</u> elevation	50000	0.3

6. Description of emergency spillway, including stilling basin. Give plan, profile, cross-section sketches with important elevations, dimen-.sions, and water surfaces. Plans available: Yes <u>No</u> Incl#

Capacity: with \_\_\_\_\_ ft. of freeboard \_\_\_\_\_\_ without freeboard \_\_\_\_\_\_ N/A normal operating capacity at \_\_\_\_\_\_ elevation

Issued 30 January 1978

% frequency

Sheet	4	of	•
Date _			
ID			

Elevation	Area (acres)		Capacity	(ac - ft)
Seo	Э	•	5	
\$\$ 5	€ <b>.</b> ⊑		- 	•
400	330	•	43:0	
915	<u> </u>		•)*	· · · ·
930	1145	•	°2703	3
940	1010		4156	5

8. As built design flood:

	Outlet works cfs. Service spillway <u>source</u> cfs.	•
	Emergency spillway cfs. Project cfs.	•
	Design freeboard feet. Expected wave feet.	•
9.	Headwater rating curve: Yes No Incl#	
10.	Tailwater rating curve: Yes <u>No</u> Incl #	
11.	Downstream channel material Rubble; erodible: Yes No	
12.	Erosion Protection:	

Upstream embankment face - Natural Vegetation Downstream embankment face - Natural Vegetation At stilling basin - Bedrock and Rubble Downstream - Rubble in channel, and natural vegetation on overbanks

NCS Form 150

		Sheet 5 of Date ID
13. Critical depths at stilling bas	in:	
Normal discharge:	•	
$Q = \ cfs, d_1 =  d_2 = \$	_ft elev., tailw	ater elev
As built project design spillway cap	acity:	•
$Q = 5000 \text{ cfs}, d_1 =, d_2 =$	ftelev., tailw	ater eleve
Other critical condition:	•	· · · · · · · · · · · · · · · · · · ·
$Q = \ cfs, d_1 =  d_2 = \$	ft elev., tailw	ater elev
Current spillway design flood:		
$Q = \ cfs, d_1 =  d_2 = \$	_ftelev., tail	ater elev
14. Critical heads across structure	: Top of dam elev. Elev. bottom channel downstream	1_860.0
At normal operating pool: <u>Q</u> Elev. <u>915</u> No flow <u>o</u>	Tailwater Elev.	Head S5'
Normal = $\underline{\circ}\infty$	360	55'
Design =		
Spillway =		
Other Critical =		
At full pool: Q	Tailwater Elev.	Head
Liev. <u>925</u> No flow		· ·
Normal = Design =		
pillway = 50000	805	60 )
Other Critical =		

N.A.C

· · · · · · · · · · · · · · · · · · ·		Date
		ID
At as built spillway	•	•
capacity pool: _Q	Tailwater Elev.	Head
Elev. No flow		
Normal =	•	
Design =		
Spillway = $50000$	I C.E.M.	60
Other Critical =	•	
At current spillway	1	
design flood:	Tailwater Elev.	Head
No flow		
Normal =		
Design =		
Spillway = 291 000	283.2	52
Other Critical =		
15. Sensitivity analysis of estimated	spillway design flo	od (SDF):
120% SDF Pool Elev. 933.4 Tai	lwater Elev. <u>385.1</u>	H_51.3
80% SDF Pool Elev. 439.0 Tai	lwater Elev. <u>880.5</u>	H _53.5
16. Will routing the current spillway cantly (by more than 10%) attenuate th	design flood throug e peak? Yes	h the pool signifi- No
a. Results of routing spillway d	esign flood through	pool
(1) Performed Se	e Incl#	
(2) Not performed	Reason:	
		-
	•	

NCS Form 150

									•		
						•			Shee Dato	t 7 of	
				•					10	·····	
	Ъ	Dom	overte	nning en	dlan bri	achina	analwaia				
	υ.	Dan	UVELLO	pprug au	d/OL DLE	security	anatysis	••			
	•	(1)	Yes _			See In	1cl#				
•		(2)	No			Re	eason:	<u>.</u>	····		
				•	•	н -				• •	•
	c.	Summ	ary of	impacts	of spi	ilway de	esign flo	ood eva	luation.	•	
		See	Incl#.				•				
17. of lse	Doe disch et: ti	es sti arge? Laide Nines	Iling The at le	basin ad uprovi sweet Lis cy lughtar	equately below the get	rhe dissig	pate ener inc 15 me tuill The 1	igy ove short water	r expect and we we the dischar	ed range	
18.	At	exist	ing sp	illway c	apacity	is eros	sion down	istream	expecte	ed?	
		Post	i wale,	dou-me	Trenin	$\frac{\partial}{\partial t} \omega$	rond		5 	- - 	
19.	Wil	l ero Poss	sion j	eopardiz $\frac{1}{17}$ $l_{a}$ ;	e safety	y of sti	ructure?	, over	long	period	
20. flo My	Doe od? drauh	tic. ju	lling apro amp stream	basin ad n locloi aloove n of th	equately	y dissig Lam hom.	pate ener may be A hy	gy for to sl dradie	spillwanort To Jamp	induce induce	n obsholy
21.	For Prol	spil	lway d ., In	esign fl The ch	ood is a	erosion	downstre	eam exp ics of	ected?	channel	•
		. <sup>5</sup>						•	en e		<b>ب</b> الم
22.	Wil	l ero	sion j	eopardiz	e safety	y of st	cucture?	•.	•	•	•
	F	robal	ly not	Ľ.					_	•	
23. spi	Has llway	down ?	stream	develop	ment cor	nstrain	ed use of	any o	utlet wo	orks or	
	·	No			•		•		•		•
24.	Has	down	stream	develop	ment com	nstrain	ed desigr	i opera	ting pla	an?	
		No		. •						•	•
		-							· .		

NCS Form 150

Sheet	8	of	
Date			
ID			

### 25. Summary of Findings:

a. Adequacy of spillway and top of dam -Dam will be overtoped by the assignment Flood, 5000 As.

See section 3.4

b. Consequences of overtopping by current spillway design flood related to breeching dam, downstream flood wave and hazard -

- c. Adequacy of outlet works and control gates -Dutlet works includes only hydro-power gates
- d. Adequacy of stilling basins -Adequate for only small discharges
- e. Adequacy of downstream erosion protection -Nutural rubble and bedrock are usequate for smaller discharges
- f. Adequacy of erosion protection at dikes, embankment, or dam -Erosion. protection is inudequate
- 8. Upstream urbanization potential and consequences -Zumbro Lake shore line is highly developed for recreational purposes and increased pressure is likely.
- h. Downstream urbanization potential and consequences -Poletential for development is high and overbank flowing will occur at large discharges

i. Consequences of dam failure at full pool and zero discharge related to downstream floodwave and hazard -

See Section 3.4

NOTE:

Mark U for unknown

N/A for not applicable

MCS Form 150