


Benton County

| | |
|------------------------|---|
| Site ID | LS0002205 |
| Site type | Leak Site |
| Location | 241 6th Ave Foley, MN 56329 Benton County |
| Release discovered | 12/03/2015 |
| Release reported | 12/03/2015 |
| Site closure date | 02/09/2017 |
| Product released | Diesel Fuel Oil #1 & #2 Gasoline, Leaded |
| Regulatory designation | Federal |



lat/long: 45.66656876,-93.90851593

Groundwater

| Drinking water contamination | Free product observed at closure | Maximum free product thickness | Groundwater contamination | Regional groundwater flow direction |
|------------------------------|----------------------------------|--------------------------------|---------------------------|-------------------------------------|
| No | No | 3 | | Unknown |

Cleanup actions

| Type | Quantity |
|-----------------------|-----------------|
| CAD Monitoring | |
| Excavation | 190 cubic yards |
| Free Product Recovery | 3 gallons |
| RI Monitoring | |

Site contacts

| Type | Name | Address | Start date | End date |
|--------------------------|---|---|------------|----------|
| has Responsible Party of | James Whitcomb | PO Box 129 Foley, Minnesota 563290129 | 12/15/2015 | |
| has Responsible Party of | James Whitcomb (Property Mgmt Director) | P.O. Box 129 Foley, Minnesota 56329 | 01/24/1990 | |
| has Responsible Party of | Benton County | PO Box 129 Foley, Minnesota 563290129 | 01/24/1990 | |
| has Responsible Party of | Benton County | 531 Dewey St Foley, Minnesota 56329 | | |
| has property owner of | Benton County Highway Dept | | 01/24/1990 | |
| has consultant of | Millsop Associates Inc | 35797 Dolney Lake Rd Crosby, | 12/15/2015 | |

| Type | Name | Address | Start date | End date |
|-------------------|------------------------|--|------------|------------|
| | | Minnesota 56441 | | |
| has consultant of | Bay West LLC | 5 Empire Dr Saint Paul, Minnesota 55103 | 12/03/2015 | 12/03/2015 |
| has consultant of | Maxim Technologies Inc | 662 Cromwell Ave Saint Paul, Minnesota 55114 | 02/22/2001 | 02/22/2001 |
| has consultant of | Maxim Technologies Inc | 662 Cromwell Ave Saint Paul, Minnesota 55114 | 10/06/1995 | 11/20/1999 |

Treatments

| Treatment type | Completed date | Soil volume (tons) | Soil volume (cubic yards) | Disposal facility |
|----------------|----------------|--------------------|---------------------------|-------------------|
| Land Treatment | 11/16/1990 | | 196 | Elwood Anderson |

Reporting

| Task | Start | End |
|---|------------|------------|
| Leak Discovered | 11/20/1989 | 11/20/1989 |
| Leak Reported | 01/24/1990 | 01/24/1990 |
| Leak Site Investigation Reopened | 01/24/1990 | 01/24/1990 |
| Soil Treatment Application Document (Form B) Preapproved | 10/11/1990 | 10/11/1990 |
| Soil Corrective Action Plan Reviewed | 08/23/1991 | 08/30/1991 |
| Soil Corrective Action Approved | 08/23/1991 | 08/30/1991 |
| Remedial Investigation Report Reviewed | 11/20/1991 | 01/23/1992 |
| Corrective Action Design Requested | 11/20/1991 | 01/23/1992 |
| Technical Review of Remedial Investigation Report Completed | 11/20/1991 | 01/23/1992 |

| Task | Start | End |
|--|------------|------------|
| Petrofund Application from Commerce Received | 02/10/1992 | 03/05/1992 |
| CSR Reviewed by Project Manager - Inadequate | 02/10/1992 | 03/05/1992 |
| Technical Review of Corrective Action Design Completed | 05/01/1992 | 07/27/1992 |
| Corrective Action Design (CAD) Reviewed | 05/01/1992 | 08/25/1992 |
| Corrective Action Design Approved | 05/01/1992 | 08/25/1992 |
| Soil Treatment Approved | 08/01/1991 | 09/04/1992 |
| Soil Treatment Application Document Reviewed | 08/01/1991 | 09/04/1992 |
| Technical Review of Monitoring Report Completed | 03/29/1993 | 04/12/1993 |
| Monitoring Report Reviewed | 03/29/1993 | 04/12/1993 |
| Monitoring Report Reviewed | 01/19/1993 | 04/12/1993 |
| Technical Review of Monitoring Report Completed | 01/19/1993 | 04/12/1993 |
| Monitoring Report Reviewed | 06/22/1993 | 06/22/1993 |
| Technical Review of Monitoring Report Completed | 06/22/1993 | 06/22/1993 |
| Technical Review of Annual or Semi Annual Report Completed | 10/12/1993 | 03/21/1994 |
| Annual or Semi Annual Report Reviewed | 10/12/1993 | 03/21/1994 |
| Technical Review of Other Report Type Not Listed Completed | 09/06/1994 | 01/17/1995 |
| Other Report Type Not Listed Reviewed | 09/06/1994 | 01/26/1995 |
| Corrective Action Design Approved | 09/06/1994 | 01/26/1995 |
| File Reviewed No Report Received | 08/30/1995 | 09/05/1995 |
| Wakeup Request Issued | 08/30/1995 | 09/05/1995 |
| Enforcement Action Response Received | 09/12/1995 | 09/12/1995 |
| More Information Requested | 09/12/1995 | 09/12/1995 |
| Monitoring Report Reviewed | 09/14/1995 | 09/15/1995 |
| Technical Review of Monitoring Report Completed | 09/14/1995 | 09/15/1995 |

| Task | Start | End |
|---|------------|------------|
| LNAPL Recovery Report Reviewed | 10/06/1995 | 12/27/1995 |
| Technical Review of LNAPL Recovery Report Completed | 10/06/1995 | 12/27/1995 |
| Monitoring Report Reviewed | 04/01/1996 | 04/11/1996 |
| Monitoring Report Reviewed | 08/14/1996 | 08/14/1996 |
| Remedial Investigation Report Reviewed | 02/03/1997 | 02/26/1997 |
| More Work Requested | 02/03/1997 | 02/26/1997 |
| Other Report Type Not Listed Reviewed | 02/14/1997 | 02/26/1997 |
| Technical Review of Remedial Investigation Report Completed | 02/03/1997 | 11/17/1997 |
| Technical Review of Annual or Semi Annual Report Completed | 01/27/1998 | 02/05/1998 |
| More Work Requested | 01/27/1998 | 03/10/1998 |
| Annual or Semi Annual Report Reviewed | 01/27/1998 | 03/10/1998 |
| Technical Review of Excavation Report Completed | 03/05/1999 | 04/19/1999 |
| Soil Treatment Application Document Reviewed | 03/06/1999 | 04/19/1999 |
| Excavation Report Reviewed | 03/05/1999 | 04/19/1999 |
| Technical Review of Annual or Semi Annual Report Completed | 11/20/1999 | 12/20/1999 |
| Site Closed | 11/20/1999 | 01/05/2000 |
| Annual or Semi Annual Report Reviewed | 11/20/1999 | 01/05/2000 |
| Leak Reported | 12/03/2015 | 12/03/2015 |
| Leak Discovered | 12/03/2015 | 12/03/2015 |
| Vapor Reassessment Completed | 09/01/2014 | 12/03/2015 |
| Site Reopen Review Completed | 12/03/2015 | 12/03/2015 |
| Standard Letter Issued | 12/21/2015 | 12/21/2015 |
| Responsible Party Determined | 12/21/2015 | 12/21/2015 |
| Technical Review of Monitoring Report Completed | 11/21/2016 | 01/26/2017 |

| Task | Start | End |
|----------------------------|------------|------------|
| Monitoring Report Reviewed | 11/21/2016 | 02/09/2017 |
| Site Closed | 02/09/2017 | 02/09/2017 |

Field work

| Notice received | Work date | Start time | Consultant | Contractor | Work type |
|-----------------|------------|------------|----------------------------|----------------|-----------------------------------|
| 01/21/2015 | 01/29/2015 | 11:00 AM | Terracon Consultants, Inc. | Thein Well | Soil Borings Soil Gas Sampling |
| 09/04/2015 | 09/11/2015 | 11:00 AM | Terracon Consultants | Thein Well Co. | Other Soil Gas Sampling |
| 08/09/2016 | 08/10/2016 | 08:00 AM | millsop assoc | | Sub-Slab Soil Gas Sampling |
| 08/25/2016 | 08/26/2016 | 08:00 AM | millsop assoc | | Sub-Slab Soil Gas Sampling |

Release details

| | |
|-------------------------------------|---------|
| Tank type | Unknown |
| Tank material | Unknown |
| Piping material | Unknown |
| Source of the release | Unknown |
| Cause of the release | Unknown |
| Release detection method | Unknown |
| Has the site ever had an E-85 tank? | Unknown |