
10 - 0481

The Annual Report of the Inspector of Mines



2009

INSPECTOR OF MINES Barry D. Lesar

OFFICE AT St. Louis County Garage Highway 135 East Virginia, Minn. 55792

PHONE: 218-742-9840

The

ANNUAL REPORT

of the

INSPECTOR OF MINES

St. Louis County, Minnesota

A Secretario

2009

INSPECTOR OF MINES

Barry D. Lesar

329 Viking Drive, Hoyt Lakes, Minnesota 55750

HOME PHONE: 218-225-3203 OFFICE PHONE: 218-742-9840

MOBILE UNIT: CD-28

E-MAIL: lesarb@co.st-louis.mn.us

Fax: 218-741-7832

ASSISTANT MINE INSPECTOR

Stanley J. Rojeski, Jr. 4554 Vermilion Trail Gilbert, Minnesota 55741

HOME PHONE: 218-865-6945 OFFICE PHONE: 218-742-9842

MOBILE UNIT: CD-27

ASSISTANT MINE INSPECTOR

Paul T. Wier

2311 Station 44 Road Eveleth, Minnesota 55734

HOME PHONE: 218-744-2806 OFFICE PHONE: 218-742-9843

MOBILE UNIT: CD-20

ASSISTANT MINE INSPECTOR

Terrance M. O'Neil

616 S. Main Street, Box 294, Biwabik, Minnesota 55708

HOME PHONE: 218-865-6978 OFFICE PHONE: 218-742-9841

MOBILE UNIT: CD-14

OFFICE AT ST. LOUIS COUNTY GARAGE

7823 HIGHWAY 135 EAST, Virginia, Minnesota 55792

PHONE: 218-742-9840

THE ST. LOUIS COUNTY BOARD OF COMMISSIONERS

District 1	Dennis Fink, Duluth, Minnesota
District 2	Steven O'Neil, Duluth, Minnesota
District 3	
District 4	Mike Forsman, Ely, Minnesota
District 5	Peg Sweeney, Gnesen Township, Minnesota
District 6	Keith Nelson, Virginia, Minnesota
District 7	Steve Raukar, Kelly Lake, Minnesota

THE ITASCA COUNTY BOARD OF COMMISSIONERS

	CON COCKTT BONTD OF COMMISSIONETTO
District 1	Lori Dowling
District 2	
District 3	
District 4	Rusty Eichorn
District 5	
Jeff Walker	
Pat Medure	Itasca County Sheriff, Itasca County Mine Inspector

THE HONORABLE BOARD OF COMMISSIONERS

ST. LOUIS COUNTY COURT HOUSE DULUTH, MN 55802-1202 ITASCA COUNTY COURT HOUSE GRAND RAPIDS, MN 55744

Dear Chairman Raukar, Chairperson Dowling and Fellow Commissioners:

The Annual Report of the Inspector of Mines for the year 2009 is herewith submitted.

While the mining industry in northern Minnesota was dealt an economic blow (as was the rest of the country), the overall condition of the industry is still good, with every reason to believe that the industry will recover from the present economic difficulties. With the recent news that the EIS for the Polymet project at the old Erie Mining Company plant site has been released to the company and was opened for public comment makes the outlook for semi-precious mining more positive than it has in years. The continued construction of the Mesabi Nugget Project outside of Aurora, along with the groundbreaking and construction start of the M.I.S. Project, along with the construction and start of production at the Magnetation projects in Itasca County, the future of mining in St. Louis and Itasca counties holds much promise for our area and our state.

On the public safety side of mining news, 2009 brought the reconstruction and reopening of Highway 169 through Chisholm. This reconstruction should alleviate any hazards associated with the old underground workings in the area. In a similar vein, the Minnesota DNR Division of Minerals, along with other agencies is in the process of expanding the underground mine mapping project. This expanded mapping should be completed in 2010 and will include the remainder of the Mesabi Range. If funding can be procured this project will be continued and the Vermillion and Cuyuna ranges will also be mapped.

The total employment for the year was 2,687 and these people worked a total of 5,197,657 manhours.

There were 80,000 tons of natural ore shipped and 17,945,710 tons of taconite products shipped from these mines. There were 33,128,352 tons of stripping and waste removed from these mines.

Inspections and visits for 2009 were as follows: Approximately 754 inspections, visits and investigations were made to the operating and non-operating mines. There were 0 fatalities and 39 lost time or serious accidents reported.

Acknowledgement and appreciation is extended to both Labor and Management for their continued interest, efforts and cooperation in the field of safety and health throughout the mines and plants in St. Louis and Itasca counties.

Respectfully submitted,

Jany D. Zen

Barry D. Lesar Inspector of Mines

St. Louis County

Excerpts from the Law On

INSPECTOR OF MINES

CHAPTER 180

MINNESOTA STATUTES

SECTION 180.03

DUTIES

SUBDIVISION 3

ABANDONED MINES

When any mine is idle or abandoned it shall be the duty of the inspector of mines to notify the person, firm, or corporation that is or has been engaged in the business of mining to erect and maintain around all the shafts, caves, and open pits of such mines a fence, barrier, appropriate signs, or combination of them, suitable to warn of the presence of shafts, caves, or open pits and reduce the possibility of accidentally falling into these shafts, caves, or open pits. If the mine has been idled or abandoned for more than 10 years, or if the person, firm, or corporation that has been engaged in the business of mining no longer exists, the fee owner shall erect the fence, barrier, or signs required by this section. The notice shall be in writing and be served upon such person, firm, corporation, or fee owner by certified mail.

SUMMARY OF STATISTICS MINES OF ST. LOUIS COUNTY, MINNESOTA

2009

Number of Mining Companies	7
Number of Mines in Operation	6
Number of Plants in Operation	6
Number of Wash Plants	0
Number of Mines Inactive	285
Number of Abandoned Mine Shafts Inspected	64
Total Number of Mines and Plants	291
Total Pellets Shipped 17,	,945,710
Total Ore Shipped	
Taconite Mined 57,	,680,916
Stripping and Waste Removal, Tons33,	
Total Material Moved, Tons Estimate	
Total People Employed	2,687
Number of Fatal Accidents, Open Pit	
Number of Fatal Accidents, Plant	
Total Number of Fatal Accidents	0
Fatalities per 1,000 People Employed	
Number of Lost-time and Time Charged Accidents	
Total Number of Man-hours Worked 5,	,197,657
Number of Visits, Inspections and Investigations	

LABOR CLASSIFICATION AND HOURLY RATES

Shift Difference:	
	Afternoon \$0.30
	Night \$0.45

2009 WAGE RATES INCENTIVE INCLUDED

Labor	Wage
Grade	Rate
1	\$18.09
2	\$19.79
3	\$21.78
4	\$22.91
5	\$24.34

Due to Contractual changes the wage structure from mine to mine has changed significantly in recent years resulting in differing methods of payment. This results in different pay scales and different average daily wages from mine to mine. This is an example of what the rates are for only one of the mines in St. Louis and Itasca counties.

Section Color C								
1905-10 (Average per year) 13,320 73 5.44 2.110 1910-11 19,918 78 3.91 2.640 1911-12 15,286 51 3.31 2.575 1912-13 16,048 44 2.74 2.705 1913-14 16,000 43 2.59 2.310 1914-15 11,430 24 2.10 2.421 1915-16 14,639 34 2.32 2.923 1916-17 14,779 22 1.51 3.391 1917-18 (Sliver Cave Disaster) 15,307 60 3.92 4.347 1918-19 14 25,349,924 14,121 36 2.55 6.010 1920-21 102 27,165,386 12,043 26 2.16 6.037 1921-22 84 13,398,525 9,688 24 3.48 4.062 1923 90 33,147,517 11,896 27 2.27 5.076 1924 75 22,808,875 11,538 21 1.82 5.144 1925 76 29,077,679 10,180 18 1.77 5.126 1926 66 32,583,943 9,225 15 1.63 5.283 1927 70 28,052,363 9,038 22 2.43 5.305 1928 59 29,704,774 8,022 9 1.12 5.230 1930 50 25,196,155 7,752 13 1,68 5.280 1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1941 63 45,874,218 7,097 60 5 0.70 6.200 1944 66 50,532,679 9,390 247 6 0.64 7.750 1944 66 50,532,679 9,390 247 6 0.64 7.750 1944 66 60,33,80,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,458 107 107 14 1.70 7.030 1944 66 60,33,80,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,458 1.65 5 7.750 1.944 1.66 60,53,80,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,495 175 175 175 1.41 7.70 1948 60 60,249,538 11,848 80 60 0.48 7.720 1949 94 42,406,528 9,680 187 7 7 7 9,480 1955 127 36,133,04 10,256 176 40,49 40 40,49 40,40			G)YEC	8	Ŋ	000	ഗ
1905-10 (Average per year) 13,320 73 5.44 2.110 1910-11 19,918 78 3.91 2.640 1911-12 15,286 51 3.31 2.575 1912-13 16,048 44 2.74 2.705 1913-14 16,000 43 2.59 2.310 1914-15 11,430 24 2.10 2.421 1915-16 14,639 34 2.32 2.923 1916-17 14,779 22 1.51 3.391 1917-18 (Sliver Cave Disaster) 15,307 60 3.92 4.347 1918-19 14,212 33 2.32 5.645 1919-20 114 25,349,924 14,121 36 2.55 6.010 1920-21 102 27,165,386 12,043 26 2.16 6.037 1921-22 84 13,398,525 9,888 24 3.48 40,62 1923 90 33,147,517 11,896 27 2.27 5.076 1924 75 22,808,875 11,538 21 1.82 5.144 1925 76 29,077,679 10,180 18 1.77 5.126 1926 66 32,583,943 9,225 15 1.63 5.283 1927 70 28,052,363 9,038 22 2.43 5.305 1928 59 29,704,774 8,022 9 1.12 5.230 1929 57 35,680,720 8,008 17 2.12 5.340 1930 50 25,196,155 7,752 13 1,68 5.280 1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1941 63 45,874,218 7,097 60 5 0.70 6.820 1944 66 50,532,679 8,495 175 12 1.41 7.70 1944 66 50,532,679 8,930 247 6 0.64 7.750 1944 66 50,532,679 8,930 247 6 0.64 7.750 1944 66 50,532,679 8,930 247 6 0.64 7.750 1945 60 60,249,538 10,286 187 7 0.72 9,480 1940 47 36,493,781 5,547 1 0.18 6,400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1943 62 51,753,320 9,597 156 7 0.73 7,440 1944 66 50,532,679 8,930 247 6 0.64 7.750 1947 79 47,293,918 8,715 153 9 1.03 8,	<u> </u>	ES	S g	2,5	<u> </u>	Ā.	710	E E
1905-10 (Average per year) 13,320 73 5.44 2.110 1910-11 19,918 78 3.91 2.640 1911-12 15,286 51 3.31 2.575 1912-13 16,048 44 2.74 2.705 1913-14 16,000 43 2.59 2.310 1914-15 11,430 24 2.10 2.421 1915-16 14,639 34 2.32 2.923 1916-17 14,779 22 1.51 3.391 1917-18 (Sliver Cave Disaster) 15,307 60 3.92 4.347 1918-19 14,212 33 2.32 5.645 1919-20 114 25,349,924 14,121 36 2.55 6.010 1920-21 102 27,165,386 12,043 26 2.16 6.037 1921-22 84 13,398,525 9,888 24 3.48 40,62 1923 90 33,147,517 11,896 27 2.27 5.076 1924 75 22,808,875 11,538 21 1.82 5.144 1925 76 29,077,679 10,180 18 1.77 5.126 1926 66 32,583,943 9,225 15 1.63 5.283 1927 70 28,052,363 9,038 22 2.43 5.305 1928 59 29,704,774 8,022 9 1.12 5.230 1929 57 35,680,720 8,008 17 2.12 5.340 1930 50 25,196,155 7,752 13 1,68 5.280 1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1941 63 45,874,218 7,097 60 5 0.70 6.820 1944 66 50,532,679 8,495 175 12 1.41 7.70 1944 66 50,532,679 8,930 247 6 0.64 7.750 1944 66 50,532,679 8,930 247 6 0.64 7.750 1944 66 50,532,679 8,930 247 6 0.64 7.750 1945 60 60,249,538 10,286 187 7 0.72 9,480 1940 47 36,493,781 5,547 1 0.18 6,400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1943 62 51,753,320 9,597 156 7 0.73 7,440 1944 66 50,532,679 8,930 247 6 0.64 7.750 1947 79 47,293,918 8,715 153 9 1.03 8,	/E/	Z	ĎΞ	Ē	Ē	-A	-A	8 8
1910-11								
1912-13	1910-11	, , , , , ,	, , , , , , , , , , , , , ,	19,918		78	3.91	2.640
1913-14								
1914-15								
1915-16								
1916-17								
1918-19	1916-17			14,779		22	1.51	3.391
1919-20		(Sliver Ca	ave Disaster)					
1920-21		11/	25 340 024	14,212				
1921-22	1							
1923 90 33,147,517 11,886 27 2.27 5.076 1924 75 22,808,875 11,538 21 1.82 5.144 1925 76 29,077,679 10,180 18 1.77 5.126 1926 66 32,583,943 9,225 15 1.63 5.283 1927 70 28,052,363 9,038 22 2.43 5.305 1928 59 29,704,774 8,022 9 1.12 5.340 1929 57 35,680,720 8,008 17 2.12 5.340 1930 50 25,196,155 7,752 13 1.68 5.280 1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1935 40 13,703,715 4,079 6 1.47 5.060 1936 42 23,322,975 4,684 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720 1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 1.03 8.720 1948 80 52,020,563 10,286 178 5 0.49 9.480 1950 109 48,671,966 10,257 159 4 0.38 10,480 1951 116 60,249,538 11,884 188 8 6.66 10,480 1955 127 36,137,304 10,381 151 2 0.19 14,850 1956 127 44,493,944 11,017 134 6 0.54 17.560 1959 89 16,055,353 9,256 93 4 0.43 22.480 1959 89 16,055,353 9,256 93 4 0.43 22.480 1959 1959 1959 19,055,353 9,256 93 4 0.43 22.480 1959 1959 1959 10,055,353 9,256 93 4 0.43 22.480 1959 1959 1959 1950 1940 10,055,353 9,256 93 4 0.43 22.480 1959 10,055,353 9,256 93 4 0.43	Į.							
1925 76 29,077,679 10,180 18 1.77 5.126 1926 66 32,583,943 9,225 15 163 5.283 1927 70 28,052,363 9,038 22 2.43 5.305 1928 59 29,704,774 8,022 9 1.12 5.230 1929 57 35,680,720 8,008 17 2.12 5.340 1930 50 25,196,155 7,752 13 1.68 5.280 1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,7781,226 4,272 2 0.47 4.830 1935 40 13,703,715 4,694 6 1.28 4.800 1937 52 36,536,326 6,356			33,147,517	11,896		27		
1926 66 32,583,943 9,225 15 1.63 5.283 1927 70 28,052,363 9,038 22 2.43 5.305 1928 59 29,704,774 8,022 9 1.12 5.230 1929 57 35,680,720 8,008 17 2.12 5.340 1930 50 25,196,155 7,752 13 1.68 5.280 1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1935 40 13,703,715 4,079 6 1.47 5.060 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356	1							
1927 70 28,052,363 9,038 22 2.43 5.305 1928 59 29,704,774 8,022 9 1.12 5.230 1929 57 35,680,720 8,008 17 2.12 5.340 1930 50 25,196,155 7,752 13 1.68 5.280 1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1935 40 13,703,715 4,079 6 1.47 5.060 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773								
1928 59 29,704,774 8,022 9 1.12 5.230 1929 57 35,680,720 8,008 17 2.12 5.340 1930 50 25,196,155 7,752 13 1.68 5.280 1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547								
1930 50 25,196,155 7,752 13 1.68 5.280 1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1935 40 13,703,715 4,079 6 1.47 5.060 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547 1 0.18 6.400 1941 63 45,874,218 7,097	1928	59	29,704,774	8,022		9	1.12	5.230
1931 32 12,270,886 4,824 4 0.83 5.260 1932 30 1,773,750 2,243 2 0.89 4,308 1933 35 10,809,167 2,843 1 0.35 4,433 1934 42 11,781,226 4,272 2 0.47 4.830 1935 40 13,703,715 4,079 6 1.47 5.060 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547 1 0.18 6.400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>								
1932 30 1,773,750 2,243 2 0.89 4.308 1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1935 40 13,703,715 4,079 6 1.47 5.060 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547 1 0.18 6.400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,7								
1933 35 10,809,167 2,843 1 0.35 4.433 1934 42 11,781,226 4,272 2 0.47 4.830 1935 40 13,703,715 4,079 6 1.47 5.060 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547 1 0.18 6.400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750			1.773.750					
1935 40 13,703,715 4,079 6 1.47 5.060 1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547 1 0.18 6.400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720								
1936 42 23,322,975 4,694 6 1.28 4.800 1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547 1 0.18 6.400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720 1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 <						2		
1937 52 36,536,326 6,356 5 0.79 6.200 1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547 1 0.18 6.400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720 1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 1.0								
1938 38 10,976,760 3,773 4 1.06 5.816 1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547 1 0.18 6.400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720 1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 1.03 8.720 1948 80 52,020,563 10,286 178 5 0.49 9.480 1949 94 42,406,528 9,680								
1939 43 24,156,258 4,589 3 0.65 6.080 1940 47 36,493,781 5,547 1 0.18 6.400 1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720 1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 1.03 8.720 1948 80 52,020,563 10,286 178 5 0.49 9.480 1949 94 42,406,528 9,680 187 7 0.72 9.480 1950 109 48,671,966								
1941 63 45,874,218 7,097 60 5 0.70 6.820 1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720 1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 1.03 8.720 1948 80 52,020,563 10,286 178 5 0.49 9.480 1949 94 42,406,528 9,680 187 7 0.72 9.480 1950 109 48,671,966 10,257 159 4 0.38 10.480 1951 116 60,249,538 11,884 188 8 0.66 10.480 1953	1939	43		4,589		3	0.65	6.080
1942 60 53,923,635 8,101 107 14 1.70 7.030 1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720 1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 1.03 8.720 1948 80 52,020,563 10,286 178 5 0.49 9.480 1949 94 42,406,528 9,680 187 7 0.72 9.480 1950 109 48,671,966 10,257 159 4 0.38 10.480 1951 116 60,249,538 11,884 188 8 0.66 10.480 1953 122 48,192,132 10,838 160 2 0.18 11.480 1953				5,547	00			
1943 62 51,753,320 9,597 156 7 0.73 7.440 1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720 1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 1.03 8.720 1948 80 52,020,563 10,286 178 5 0.49 9.480 1949 94 42,406,528 9,680 187 7 0.72 9.480 1950 109 48,671,966 10,257 159 4 0.38 10.480 1951 116 60,249,538 11,884 188 8 0.66 10.480 1952 122 48,192,132 10,838 160 2 0.18 11.480 1953 122 60,776,174 12,079 215 4 0.33 12.160 1954								
1944 66 50,532,679 9,390 247 6 0.64 7.750 1945 56 47,544,509 8,495 175 12 1.41 7.720 1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 1.03 8.720 1948 80 52,020,563 10,286 178 5 0.49 9.480 1949 94 42,406,528 9,680 187 7 0.72 9.480 1950 109 48,671,966 10,257 159 4 0.38 10.480 1951 116 60,249,538 11,884 188 8 0.66 10.480 1952 122 48,192,132 10,838 160 2 0.18 11.480 1953 122 60,776,174 12,079 215 4 0.33 12.160 1954 121 49,845,118 9,925 157 4 0.40 12.560 1955 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
1946 60 38,380,361 7,100 167 6 0.84 7.720 1947 79 47,293,918 8,715 153 9 1.03 8.720 1948 80 52,020,563 10,286 178 5 0.49 9.480 1949 94 42,406,528 9,680 187 7 0.72 9.480 1950 109 48,671,966 10,257 159 4 0.38 10.480 1951 116 60,249,538 11,884 188 8 0.66 10.480 1952 122 48,192,132 10,838 160 2 0.18 11.480 1953 122 60,776,174 12,079 215 4 0.33 12.160 1954 121 49,845,118 9,925 157 4 0.40 12.560 1955 127 36,137,304 10,381 151 2 0.19 14.850 1956 127 44,493,944 11,017 134 6 0.54 17.560 195	1944	66		9,390		6	0.64	
1947 79 47,293,918 8,715 153 9 1.03 8.720 1948 80 52,020,563 10,286 178 5 0.49 9.480 1949 94 42,406,528 9,680 187 7 0.72 9.480 1950 109 48,671,966 10,257 159 4 0.38 10.480 1951 116 60,249,538 11,884 188 8 0.66 10.480 1952 122 48,192,132 10,838 160 2 0.18 11.480 1953 122 60,776,174 12,079 215 4 0.33 12.160 1954 121 49,845,118 9,925 157 4 0.40 12.560 1955 127 36,137,304 10,381 151 2 0.19 14.850 1956 127 44,493,944 11,017 134 6 0.54 17.560 1957 124 50,093,275 12,804 144 6 0.47 17.560								
1948 80 52,020,563 10,286 178 5 0.49 9.480 1949 94 42,406,528 9,680 187 7 0.72 9.480 1950 109 48,671,966 10,257 159 4 0.38 10.480 1951 116 60,249,538 11,884 188 8 0.66 10.480 1952 122 48,192,132 10,838 160 2 0.18 11.480 1953 122 60,776,174 12,079 215 4 0.33 12.160 1954 121 49,845,118 9,925 157 4 0.40 12.560 1955 127 36,137,304 10,381 151 2 0.19 14.850 1956 127 44,493,944 11,017 134 6 0.54 17.560 1957 124 50,093,275 12,804 144 6 0.47 17.560 1958 90 30,495,093 10,250 83 0 0.00 18.400 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>								
1949 94 42,406,528 9,680 187 7 0.72 9.480 1950 109 48,671,966 10,257 159 4 0.38 10.480 1951 116 60,249,538 11,884 188 8 0.66 10.480 1952 122 48,192,132 10,838 160 2 0.18 11.480 1953 122 60,776,174 12,079 215 4 0.33 12.160 1954 121 49,845,118 9,925 157 4 0.40 12.560 1955 127 36,137,304 10,381 151 2 0.19 14.850 1956 127 44,493,944 11,017 134 6 0.54 17.560 1957 124 50,093,275 12,804 144 6 0.47 17.560 1958 90 30,495,093 10,250 83 0 0.00 18.400 1959 89 16,055,353 9,256 93 4 0.43 22.480								
1951 116 60,249,538 11,884 188 8 0.66 10.480 1952 122 48,192,132 10,838 160 2 0.18 11.480 1953 122 60,776,174 12,079 215 4 0.33 12.160 1954 121 49,845,118 9,925 157 4 0.40 12.560 1955 127 36,137,304 10,381 151 2 0.19 14.850 1956 127 44,493,944 11,017 134 6 0.54 17.560 1957 124 50,093,275 12,804 144 6 0.47 17.560 1958 90 30,495,093 10,250 83 0 0.00 18.400 1959 89 16,055,353 9,256 93 4 0.43 22.480								
1952 122 48,192,132 10,838 160 2 0.18 11.480 1953 122 60,776,174 12,079 215 4 0.33 12.160 1954 121 49,845,118 9,925 157 4 0.40 12.560 1955 127 36,137,304 10,381 151 2 0.19 14.850 1956 127 44,493,944 11,017 134 6 0.54 17.560 1957 124 50,093,275 12,804 144 6 0.47 17.560 1958 90 30,495,093 10,250 83 0 0.00 18.400 1959 89 16,055,353 9,256 93 4 0.43 22.480								
1953 122 60,776,174 12,079 215 4 0.33 12.160 1954 121 49,845,118 9,925 157 4 0.40 12.560 1955 127 36,137,304 10,381 151 2 0.19 14.850 1956 127 44,493,944 11,017 134 6 0.54 17.560 1957 124 50,093,275 12,804 144 6 0.47 17.560 1958 90 30,495,093 10,250 83 0 0.00 18.400 1959 89 16,055,353 9,256 93 4 0.43 22.480								
1954 121 49,845,118 9,925 157 4 0.40 12.560 1955 127 36,137,304 10,381 151 2 0.19 14.850 1956 127 44,493,944 11,017 134 6 0.54 17.560 1957 124 50,093,275 12,804 144 6 0.47 17.560 1958 90 30,495,093 10,250 83 0 0.00 18.400 1959 89 16,055,353 9,256 93 4 0.43 22.480								
1955 127 36,137,304 10,381 151 2 0.19 14.850 1956 127 44,493,944 11,017 134 6 0.54 17.560 1957 124 50,093,275 12,804 144 6 0.47 17.560 1958 90 30,495,093 10,250 83 0 0.00 18.400 1959 89 16,055,353 9,256 93 4 0.43 22.480								
1957 124 50,093,275 12,804 144 6 0.47 17.560 1958 90 30,495,093 10,250 83 0 0.00 18.400 1959 89 16,055,353 9,256 93 4 0.43 22.480	1955	127	36,137,304	10,381	151	2	0.19	14.850
1958 90 30,495,093 10,250 83 0 0.00 18.400 1959 89 16,055,353 9,256 93 4 0.43 22.480								
1959 89 16,055,353 9,256 93 4 0.43 22.480								
1 1000 00 00,000,010 11,101 100 2 0.10 22,700	1960	95	39,526,879	11,797	132	2	0.16	22.430
1961 85 33,169,291 9,200 51 4 0.43 22.430	1961	85			51		0.43	22.430

·									
i i	YEAK	MINES	TONS	EMPLOYED	INJURED	FATALS	FAT/1000	WAGES	
1 19	962	46	23,269,349	8,676	57	1	0.11	22.430	
	963	61	35,255,178	7,671	30	2	0.26	22.430	
1	964	42	39,115,088	8,102	26	1	0.12	22.430	
	965	54	40,891,345	8,305	53	Ö	0.00	22.430	
	966	49	44,412,473	9,445	56	4	0.43	22.430	
	967	51	41,216,870	8,825	52	4	0.44	23.760	
1	968	53		9,125					
	969	51	43,078,879		55 50	2	0.22	25.640	
			34,628,234	9,394	58	0	0.00	27.430	
1	970	49	33,648,268	9,631	71	5	0.52	28.520	
	971	50	32,687,511	9,441	58	0	0.00	32.480	
	972	46	35,100,156	9,431	63	0	0.00	34.096	
	973	47	46,076,814	10,131	58	4	0.40	35.352	
	974	49	51,745,763	10,667	60	1	0.09	44.360	
	975	51	45,394,814	10,864	71	0	0.00	45.842	
	976	52	41,425,833	11,514	77	1	0.09	47.368	
1	977	24	26,556,566	10,840	82	2	0.19	56.682	
	978	26	50,806,547	13,056	138	1	0.08	64.344	
	979	26	54,530,338	13,267	164	0	0.00	70.832	
19	980	18	42,076,497	11,441	107	1	0.09	80.112	
19	981	12	47,300,056	11,630	96	0	0.00	89.472	
19	982	11	22,335,570	7,626	44	0	0.00	94.192	
19	983	9	26,843,983	5,935	50	2	0.34	84.19	
19	984	9	30,463,941	6,305	55	0	0.00	87.39	
19	985	9	31,948,722	5,539	29	0	0.00	90.60	
1	986	9	26,608,768.51	5,250	33	0	0.00	94.19	
	987	9	30,063,909	4,857	26	1	0.21	94.19	
1	988	9	37,250,242.97	4,546	41	1	0.18	94.19	
	989	9	38,421,803	5,664	55	2	0.35	94.19	
	990	9	41,441,888	6,379	40	1	0.16	94.19	
	991	10	38,420,014	6,468	49	Ó	0.00	94.19	
1	992	10	37,684,439	6,325	110	Ö	0.00	106.94	
	993	9	39,338,920	5,953	133	Ö	0.00	106.94	
	994	9	43,976,323.01	6,051	97	1	0.17	93.936	
	995	9	47,030,820.33	6,005	87	Ö	0.00	97.936	
	996	8	46,144,620.64	6,032	96	Õ	0.00	101.936	
1	997	8	46,978,014	6,129	84	Ö	0.00	103.616	
1	998	8	46,862,734	5,962	114	1	0.17	105.936	
	999	9	43,136,042		99	Ó	0.00	105.936	
•				5,633					
1	000	9	44,806,128	5,610.7	77 60	1	0.18	109.936	
1	001	8	34,144,559.29	4,212	60	0	0.00	113.936	
1	002	8	39,087,907	4,036	60	0	0.00	113.936	
	003	8	35,282,267	4,177	35	0	0.00	121.936	
ı	004	8	42,059,597	3,444	24	0	0.00	145.384	Augraga/Day
1	005	8	40,464,088.92	3,568	29	0	0.00	178.40	Average/Day
1	006	7	39,617,873	3,714	14	1	0.27	178.40	Average Day
1	007	7	38,041,615.6	3,724	13	2	0.54	187.848	
1	800	7	40,599,311	3,732	26	0	0.00	182.40	
	009	7	18,025,710	2,687	39	0	0.00	201.44	see pg. 4 wages

REPORT TO COUNTY INSPECTOR OF MINES

(Minnesota Statutes 180)

ORE SHIPPED FROM MINES, TONS OF STRIPPING REMOVED NUMBER OF PEOPLE EMPLOYED, MINES OF ST. LOUIS COUNTY, MINNESOTA YEAR ENDING DECEMBER 31, 2009

								
MINES AND SUPERINTE	NDENTS	TONS OF NATURAL ORE SHIPPED	TONS OF TACONITE PELLETS SHIPPED	TOTAL TACONITE MINED	TONS STRIPPING WASTE *	AVG. NO. PEOPLE EMPLOYED PLANTS/PITS	MAN HOURS	MONTHS WORKED
Operations Ma	nager	_						
Per Transfer		Concentrate -	/	11,083,501	10,226,167	500	878,752	12
UNITED TACC Jack Tuomi - V	NITE LLC AI P & General Ma	Tonnages in Long	-,	, ,	· -,- 			
Keewatin Tacc		ca Co. Production	· _	98,314	182,400	Mine 23	47,159	12
Division of US		uis Co. Production	0	0	Chana Wara	Plant 28	58,920	12 12
Minnesota Ore	Operations				Shops, ware	house & Misc. 35	72,980	12
HIBBING TAC Ed Latendress		Production Shipped From Plant	1,701,646	6,349,650	6,757,683	310	682,104	12
MINORCA MIN			<u>.</u>					
Minorca Mine		ages in Long Tons	1,464,449 - Flux	5,061,025	4,615,025	330	564,566	12
J.H. Holmes, V	ice President, C	perations I						
NORTH SHOF MINING COMI Babbitt, Silver M. Mlinar, Gen	PANY All To Bay	onnages in Long Tor	ns 3,230,294	9,347,194	4,993,737	520	941,899	9

rage /

rage o

REPORT TO COUNTY INSPECTOR OF MINES (Minnesota Statutes 180)

ORE SHIPPED FROM MINES, TONS OF STRIPPING REMOVED NUMBER OF PEOPLE EMPLOYED, MINES OF ST. LOUIS COUNTY, MINNESOTA YEAR ENDING DECEMBER 31, 2009

MINES AND SUPERINTENDENTS	TONS OF NATURAL ORE SHIPPED	TONS OF TACONITE PELLETS SHIPPED	TOTAL TACONITE MINED	TONS STRIPPING WASTE *	AVG. NO. PEOPLE EMPLOYED PLANTS/PITS	MAN HOURS	MONTHS WORKED
MESABI MINING, LLC Tom Lutes, Mine Manager MESABI NUGGET, LLC Steve Rutherford - Operations M	So there are r		nstruction phase for mployment figures for			ng phase for th	ne Mine.
USS CORPORATION, Minneson S. Coleman, Gen. Mgr. Minntac Plant, Mt. Iron All Tonn Minntac Mine Minntac Plant Shop, Warehouse, & Miscellane	ages in Gross Ton		25,741,232	1	ance - 398 Plant - 422 ation - 91	829,840 880,473 189,364	12 12 12
MAGNETATION, INC. Larry Lehtinen, Chairman Nashwauk, MN	Mesabi Chi 80,000 Met	ef 3 Mine ric Ton All from Ita	sca County		30	<u>.</u> 51,600	10
TOTALS	80,000	17,945,710	57,680,916	33,128,352	2,687	5,197,657	12
TOTAL RAW ORE	80,000						
TOTAL RAW ORE AND PELLETS		18,025,710	TOTAL NATURAL & TACONITE SHII				

REPORT TO COUNTY INSPECTOR OF MINES

(Minnesota Statutes 180)

ORE SHIPPED FROM MINES, TONS OF STRIPPING REMOVED NUMBER OF PEOPLE EMPLOYED, MINES OF ST. LOUIS COUNTY, MINNESOTA YEAR ENDING DECEMBER 31, 2009

NON-FERROUS MINES AND SUPERINTENDENTS	TONS OF PRODUCT SHIPPED	TOTAL ORE MINED	TONS STRIPPING WASTE *	AVG. NO. PEOPLE EMPLOYED PLANTS/PITS	MAN HOURS	MONTHS WORKED
SOI EI IIIVI EI VOEI VIS	Si iii i LD	MINALD	WASIL	FLANISIFIIS	1100113	WORKED

Polymet Mining Corp.

NON-FERROUS PROPERTY, IN DEVELOPMENT, NOT IN PRODUCTION AT THIS TIME

TOTAL MATERIAL MOVEMENT FERROUS AND NON-FERROUS

- * Total Tonnage of both waste rock and overburden removed to expose the ore body
- ** Tonnage Used to Determine Total Production Shipped for the year

MINING COMPANIES, MINE OPERATIONS, SAFETY PERSONNEL AND OTHER AGENCIES

UNITED STATES STEEL CORPORATION

Minnesota Ore Operations KEEWATIN TACONITE P.O. Box 217 Keewatin, Minnesota 55753

Phone: 218-778-8798

Jeremy Smolich Michael Bakk William Getty Tim Kalish	General Manager Plant Manager Plant Manager Area Manager - Electrical & Mine Maintenance Area Manager, Mine Operations & Crusher Area Manager - Plant Operations & Maintenance Labor Relations
•	- · · · · · · · · · · · · · · · · · · ·
	· ·
John Skube	Labor Relations
Laurie Potter	Manager, Safety & I.H.
Scott Karpinen	Sr. Staff Supervisor of Safety & I.H.
Jerry Orrell	Staff Supervisor, Safety & I.H.

* * * * * *

UNITED TACONITE LLC

P.O. Box 180 Eveleth, MN 55734 Phone: 218-744-7800

Jack Tuomi	Vice President - General Manager
Santi Romani	Senior Area Manager, Plant Operations
Mike Smith	Area Manager, Pit Operations
Dave Sefcovic	Area Manager, Technical Services
Todd Nelson	Area Manager, Finance
John Baxter	Area Manager, Human Resources
Jon LaMusga	Section Manager, Materials
Lyle Johnston	Area Manager, Maintenance
Dave Evans	Area Manager, Safety
Jason Aagenes	Manager, Minnesota and Canadien
	Environmental Services
Rob Bigelow	Section Manager - Six Sigma

HIBBING TACONITE COMPANY

P.O. Box 589 Hibbing, Minnesota 55746 Phone: 218-262-5950

	General Manager Area Manager - Technical Services
	Sr. Area Manager - Financial Control
	Sr. Area Manager - Mining
P.A. Carlson	Area Manager - Plants
D.A. Weiberg	Area Manager - Maintenance
J.C. Tamminen	Area Manager - Technical Support Manager
H.E. Drews	Area Manager - Information Technology
E.G. Bryant	Sr. Area Manager - Human Resources
A.J. Bakk	. Sr. Section Manager - Safety & Loss Control
A.S. McDowel	Section Manager - Environmental
R.W. Hess	Section Manager - Procurement

* * * * *

MESABI MINING, LLC

P.O. Box 235 6500 County Road 666 Hoyt Lakes, Minnesota 55750 Phone: 218-225-6000

Fax: 218-225-0600

Dave Bednarz	Vice President - Iron Resources,
	Steel Dynamics, Inc.
Tom Lutes	Mine Manager, Mesabi Mining, LLC
Steve Rutherford	Operations Manager, Mesabi Nugget, LLC
Jeff Hansen	Engineering Manager, Mesabi Nugget, LLC

ARCELOR MITTAL MINORCA MINE, INC.

5950 Old Hwy. 53 P.O. Box 1 Virginia, Minnesota 55792 Phone: 218-749-5910 Fax: 218-749-3420

DIRECTORS

Louis Schorsch, Michael Rippey

ARCELOR - MITTAL MINING OFFICERS

Michael Pippov	Procident and CEO
	President and CEO
Mark Whalen	Vice President and General Manager
Andy Harshaw	Executive Vice President
	. Executive Vice President, Sales & Marketing
John Brett Vic	e President, Corporate Planning and Analysis
Jonathan H. Holmes	Vice President, Operations
Om Mandhana	Vice President, Procurement
Greg Ludkovsky	Vice President, Technology
	Vice President, Human Resources
Vaidya Sethuramen . \	/ice President, Finance & Chief Account Officer
Thomas A. McCue	Treasurer
William Mundell	Assistant Treasurer
Jay Lazar	Secretary
	Assistant Secretary
Marc R. Jeske	Assistant Secretary

SECTION MANAGERS

Darrell Maki	Manager - Plant
William Bond Division Manager -	Business & Operating Technology
Gerald Golobich Manager - H	uman Resources/Labor Relations
Scott Harrison	Manager - Pit
Karla Heritage - McKenzie	Manager - Safety
Thomas Cossalter	Manager - Purchasing
Alvis Pace	Controlle

* * * * * * *

NORTHSHORE MINING COMPANY

10 Outer Drive Silver Bay, Minnesota 55614 Phone: 218-226-4125

NORTHSHORE MINING BABBITT MINE BABBITT, MINNESOTA 55706

Phone: 218-827-2101

Michael Mlinar	General Manager
James Korpi	Operations Manager
	Maintenance Manager
Chuck Renwald	Tech Services Manager
John Sandstrom	Railroad Manager
Karl Kerschen	Human Resources Manager
Scott Gischia	Environmental Manager
William Bundschuh	Silver Bay Power Manager
Robert Willis	Safety Manager
Scott Blood	Plant Safety Representative
Maria Strand	Plant Safety Associate
Dean DeBeltz	Mine Safety Representative

UNITED STATES STEEL CORPORATION

Minnesota Ore Operations MinnTac P.O. Box 417 Mt. Iron, MN 55768

Phone: 218-749-7299

Scott Coleman	General Manager
Bruce Kniivila	Division Manager - Mining, Maintenance
Scott Vogle	Division Manager, Concentrating and Crushing
Doug Johnson	Division Manager, Ore Movement and ISO
John Skube	Manager - Employee Relations
Laurie Potter	Manager - Safety & I.H.
Scott Karpinen	Sr. Staff Supervisor - Safety & I.H.
Robert Youngman	Staff Supervisor - Safety & I.H.
Kent Swanson	Staff Supervisor - Safety & I.H.
John Zupin	Staff Supervisor - Safety & I.H.

* * * * * *

POLYMET MINING

P.O. Box 475 6500 County Road 666 Hoyt Lakes, MN 55750

OFFICERS

William Murray	Chairman of the Board
Joseph Scipioni	. President and Chief Executive Officer
Douglas Newby	Chief Financial Officer
Phillip Brodie-Hall Executiv	e Vice President - Project Construction
Latisha Gietzen Vic	e President of Public, Government and
	Environmental Affairs

STAFF

James Tieberg	Division Manager - Mining
James Scott	Manager - Environmental
Richard Patelke	Project Geologist
Dave Draves	Site Controller
Stephen DeVaney	Procurement Manager
Paul Brunfelt	Division Manager of Plant
Kevin Pvlka Manager of Env	ironmental Permitting & Compliance

* * * * * *

MAGNETATION, INC.

Red Rock Business Center 832 First Street, Suite 130 Nashwauk, Minnesota 55769 Phone: 218-885-0043

Larry Lehtinen	Chairman, President & CEO
Matt Lehtinen	Vice President of Marketings
David J. Chappie	. Vice President of Operations & Engineering
Hope Wilson	CFO
Marty Halverson	Senior Engineer
Luke Lehtinen	Project Engineer

* * * * * * *

ALWORTH LAND & IMPROVEMENT COMPANY

1605 Alworth Building 306 W. Superior Street Duluth, Minnesota 55802 Phone: 218-722-0816

R.K. Prescott	Chairman
Nicholas B. Alworth	Vice Chairman
Steven G. LaFlamme	President
Roger D. Wedin	Executive Vice President
George W. Kratzner, II	Treasurer
Thea M. Barnes	Secretary

* * * * * *

CONGDON MINERAL MANAGEMENT INC.

3920 13 Ave. E., Suite 7 Hibbing, Minnesota 55746-3672 Phone: 218-262-0799

Fax: 206-203-0098

John P. Congdon	President
David G. Meineke	Vice President
Ann L. Albrecht	. Assistant Secretary and Treasurer

* * * * * *

EVELETH FEE OFFICE, INC.

301 McKinley Avenue P.O. Box 521 Eveleth, Minnesota 55734-0521

> Phone: 218-744-4646 Fax: 218-744-2149

Daniel L. England	President
Thomas J. Malkovich	Vice President/Manager of Mines
Beverly A. Saranpaa	Administrative Assistant

* * * * * *

GREAT NORTHERN IRON ORE PROPERTIES

801 East Howard Street P.O. Box 429 Hibbing, Minnesota 55746-0429 Phone: 218-262-3886

Fax: 218-262-4295

J.S. Micallef	President and CEO
J.A. Swearingen	Trustee
R.W. Staehle	Trustee
R.A. Stein	Trustee
T.A. Janochoski	Vice President and CFO
R.P. Johnson	Manager of Mines
K.A. Baehr	Manager of Accounting

* * * * * *

HARTLEY OFFICE

740 East Superior Street Duluth, Minnesota 55802 Phone: 218-723-8060

Mark Myles Trust Manager

* * * * * *

IRON MINING ASSOCIATION OF MINNESOTA

324 West Superior Street Suite 502 Duluth, Minnesota 55802 Phone: 218-722-7724 www.taconite.org

Craig Pagel President

OFFICERS

Ed Latendresse, Board Chair	Hibbing Taconite
William Bond	Arcelor Mittal, Minorca Mine
	Arcelor Mittal, Minorca Mine
	Cliffs Natural Resources
Mike Mlinar	Northshore Mining
Maureen Talarico	Cliffs Natural Resources
Tim Tomsich	Hibbing Taconite
Jack Tuomi	United Taconite
Scott Coleman	Minnesota Ore Operations
Scott Vagle	US Steel - Minntac
Jeremy Smolich	US Steel - Keetac
	US Steel
Larry Lehtinen	Magnetation
Environmental; Committee	Chrissy Bartovich
Public Information Committee	Bob Poulter
	Laurie Potter
•	

ONONDAGA IRON COMPANY

740 East Superior Street Duluth, MN 55802 Phone: 218-723-8060

Douglas H. Lewis	Chief Financial Officer
Kenneth Maine	Chief Executive Officer
بلد بلد بلد بلد بلد	

MINING MINNESOTA

P.O. Box 16666 Duluth, Minnesota 55816 Phone: 218-393-2301

E-Mail: fongaro@miningminnesota.com

Frank Ongaro Executive Director

MERIDEN ENGINEERING LLC

1910 East 8th Avenue P.O. Box 650 Hibbing, Minnesota 55746 Phone: 218-262-6127

SUPERIOR MINERALS RESOURCES LLC

1910 East 8th Avenue P.O. Box 650 Hibbing, Minnesota 55746 Phone: 218-262-6127 www.superiormineral.com

MESABI MINERAL ASSOCIATION

By Oneida Realty Company 1605 Alworth Building 306 W. Superior Street Duluth, Minnesota 55802 Phone: 218-722-0816

GLOBAL MINERALS ENGINEERING, LLC

3920 13th Ave. E., Suite 7 Hibbing, Minnesota 55746-3672 Phone: 218-262-0799 Fax: 206-203-0098

David G. Meineke President & CEO

* * * * * *

MINNESOTA DEPARTMENT OF NATURAL RESOURCES

500 Lafayette Road St. Paul, Minnesota 55155 (651) 259-5959 FAX (651) 296-5939

M. Holsten	Commissioner
L. Martinson	Deputy Commissioner
L. Kramka	Assistant Commissioner
M.K. Vadis	Director, Division of Lands and Minerals (LAM)

Division of Lands and Minerals 1525 E. Third Avenue Hibbing, Minnesota 55746 (218) 231-8484 FAX (218) 262-7328

J. Engesser Asst. Director, Division of Lands and Minerals P. Clevenstine Manager, Engineering & Mineral Development

* * * * * *

STATE OF MINNESOTA IRON RANGE RESOURCES MINELAND RECLAMATION 801 SW Highway 169, Suite 2 Chisholm, Minnesota 55719

Phone: (218) 254-7967 Fax: (218) 254-7973

D. Jordan	Mining and Minerals Program Supervisor
B. Itkonen	Mineland Reclamation Specialist, Sr.
G. Dormanen	Mineland Reclamation Specialist
S. Perkovich	Office & Administration Specialist, Sr.
J. Plummer	. Laurentian Vision and Real Property Coordinator

* * * * * *

IRON RANGE RESOURCES 4261 HIGHWAY 53 SOUTH P.O. BOX 441

EVELETH, MN 55734

Phone: (218) 744-7400 or 800-765-5043

S. Layman	Commissioner Iron Range Resources
B. Hiti	. Deputy Commissioner, Iron Range Resources
M. Sjoberg	Director, Development Strategies

* * * * * *

RGGS Lands & Minerals LTD., L.P. 202 2nd Avenue South Virginia, MN 57792 Phone: (218) 749-1291

Fax: (218) 749-1294

* * * * * *

MINNESOTA MINE INSPECTORS

St. Louis County

Barry D. Lesar	Inspector of Mines
Stanley J. Rojeski, Jr	
Paul T. Wier	
Terrance M. O'Neil	

OFFICE AT ST. LOUIS COUNTY GARAGE

Highway 135 East Virginia, Minnesota 55792 Phone: 218-742-9840

* * * * * *

UNITED STATES DEPARTMENT OF LABOR MINE SAFETY AND HEALTH ADMINISTRATION

515 W. 1st Street #333 Duluth, Minnesota 55802-1302 COMM: 218-720-5448 FAX: 218-720-5650

Duluth Duty Field Station COMM: 218-720-5448

DISTRICT OFFICE

	District Manager Assistant District Manager
	Supv. Spec. Investigator
	Mine Safety & Health Specialist
Clopine 17 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	(Health Specialist)
William H. Pomroy Mine Safety 8	& Health Specialist (Staff Assistant)
	Mine Safety & Health Specialist
Wayne L. Lundquist Mir	ne Safety & Health Specialist (CLR)
Stephen W. Field	Mine Safety & Health Specialist
Mary M. Mikulich Sup	v. Management & Program Analyst
Devon R. Willeck	IT Specialist
Jenna L. Nelson	District Secretary
Debra J. Johnson Mine	Safety and Health Technician (OA)
Kenneth L. Bickel	Safety Specialist

DULUTH DUTY FIELD STATION

Dale E. Hedman	. Mine Safety & Health Inspector
Daniel J. Goyen	. Mine Safety & Health Inspector
Robert A. Marincel	Mine Safety & Health Inspector

HIBBING FIELD OFFICE

522 East Howard Street, Suite 201A Hibbing, Minnesota 55746 Phone: 218-262-5205 Fax: 218-262-1296

MINNESOTA DEPARTMENT OF REVENUE

600 North Robert Street St. Paul, Minnesota 55146

Phone: (651) 556-3100 Fax: (651) 297-5309

Ward Einess Commissioner
Roger Swanson Director, Special Taxes Division

Minerals Tax Office 612 Pierce St. Eveleth, Minnesota 55734-1611

Phone: (218) 744-7424 Fax: (218) 744-7421

* * * * * *

INTERNATIONAL UNION OF OPERATING ENGINEERS

Local No. 49, 49A, 49B, 49C, 49D, and 49E Minnesota, North Dakota, South Dakota 8381 Enterprise Drive N Virginia, MN 55792

Phone: 218-741-8190 - Virginia Phone: 218-724-3840 - Duluth

Thomas Pariseau	President
Daniel Kingsley	Officer
J. Dale Long	Officer
Brent Pykkonen	Officer (Duluth)
Janet Haley	Secretary
Pam Fairchild	Secretary (Duluth)

* * * * * *

UNITED STEEL WORKERS OF AMERICA DISTRICT 11

MINNEAPOLIS OFFICE

Phone: 612-623-8045

EVELETH SUB-DISTRICT OFFICE

Phone: 218-744-2757 Fax: 218-744-7926

John Rebrovich Staff Representative
Cathy Warner Staff Representative
Peggy May Staff Representative

UNITED STEEL WORKERS OF AMERICA LOCAL UNITS

LOCAL #6860 UNITED TACONITE LLC

Phone: 218-744-4480

John Motley	President
Joe Fredrickson	Vice President
Amy Hutkowski	Recording Secretary
Steve Lere	Financial Secretary
Jim Ravnikar	Treasurer
Brian Lahti	Safety Coordinator
Larry Roberts	Plant Safety Chairman
Paul Horoshak	Mine Safety Chairman

LOCAL #2660 KEEWATIN TACONITE

Phone: 218-778-6909

Jack Thronson	President
Lorne Middlestead	Safety Representative
David Mlakar	Chairman, Safety Committee
Joe Ferris	Area Chair, Pellet Plant
Kevin Noonan	Area Chair, Concentrator
Cliff Tobey	Area Chair, Shops
Dan Grzybowski	Area Chair, Pit
Harlee Sirjord	Area Chair, Pond
Tom Damjanovich	Area Chair, Crusher

LOCAL #2705 HIBBING TACONITE COMPANY

Phone: 218-254-2492 Fax: 218-254-7100

4. 115 W. Lake Street, Chisholm, MN 55719

Frank Jenko	President
Mike Wright	USW International Safety Department
Bob Brown	Chairman, Safety Committee
Rich Novak	Alternate

LOCAL #6115 MITTAL STEEL USA, MINORCA MINE INC.

Phone: 218-741-3310

Ray Pierce	President
Tom French	
Jim Labernik	Sub Chair, Truck Shop
Jim Kottke	Sub Chair, Training

LOCAL #1938 USX - MINNTAC MINE

Phone: 218-741-0887

Mike Woods	President
Jon Malek	Vice President
Dave Chesser	Recording Secretary
Chad Daniels	Financial Secretary
Paul Centa	Treasurer
Tim Carlson	Safety Committee Chairman
Mark Hagsten	Safety Committee Co-Chairman
Dennis Jensrud	Safety Coordinator - Plants
Rodney Moberg	Safety Representative, Mine/Shops
Lowell Carlon	Safety Representative, Concentrator/Crushers
Dave Toole	. Safety Representative, Agglomerators I, II, III

NON-FATAL LOST-TIME AND SERIOUS ACCIDENTS

ARCELOR MITTAL, MINORCA MINE, INC.

Driller, Date of Accident - March 10, 2009, A driller was exiting her drill. As she stepped off of the ladder, she landed on a rock with her left foot, causing her foot to twist in an awkward fashion. This resulted in a sprained left ankle. Days Lost - 9

UNITED TACONITE LLC

MINE

Mine Mechanic, Date of Accident - February 9, 2009. Injured was assisting a shovel operator in the replacement of a cracked cover plate on his shovel. The operator tapped the edge of the cover plate causing a piece of metal to splinter off and strike the mechanic in the face. This resulted in the piece being lodged in his face. Days Lost - 1

Warehouse Person, Date of accident - March 12, 2009. Injured was shifting a filter on a storage rack inside the warehouse. While lifting the corner of the filter he suffered a strain/sprain to the lower back. Days Lost - 16

Mine Operations, Date of Accident - April 15, 2009. Injured was removing blast hole plugs from a blast pattern in preparation to load the holes with explosives. When Injured stepped off the cutting pile of the hole, he rolled his ankle. This resulted in a strain/sprain to the right ankle. Days Lost - 6

Mine Maintenance, Date of Accident - July 13, 2009. Injured was working on a Production Truck, the driver was unaware of his presence and started to drive away. Injured jumped from the truck to the ground to avoid being struck by the Production Truck. This resulted in an injured knee. Days Lost 113

Mine Maintenance, Date of Accident - October 28, 2009. Injured was performing a brake job on light fleet vehicle. He was compressing the brake caliper with a clamp. As he was tightening the clamp he felt a pain in his arm. This resulted in a strain/sprain. Days Lost - 19

Mine Maintenance, Date of Accident - October 30, 2009. Injured was lifting some mud flaps for a Production Truck when he felt a pain in his back. This resulted in a strain/sprain to the back. Days Lost - 50

Mine Maintenance, Date of accident - November 2, 2009. Injured was in the process of removing the wheel from a loader. The employee was using an impact wrench with an extension to remove the nuts. The impact wrench slipped off the bolt and injured banged his elbow against the wheel. This resulted in a contusion to the elbow. Days Lost - 4

Mine Maintenance, Date of Accident - December 3, 2009. Injured was walking down a stairway at the dust collector. When he reached the bottom step his boot slipped on some gravel. This resulted in a fractured ankle. Days Lost - 18

Mine Maintenance, Date of Accident - December 27, 2009. Injured was removing a bolt using an impact wrench. When he felt the bolt begin to spin freely, he reached behind the bolt to investigate and cut his finger on a sharp edge. This resulted in a laceration to the finger tip. Days Lost - 12

Mine Maintenance, Date of Accident - December 31, 2009. Injured was guiding a shovel into the truck shop. Rubber was placed on the floor to protect the concrete from the shovel tracks and injured slipped on the rubber. This resulted in a strain/sprain to the back. Days Lost - 1

PLANT

Pellet Maintenance, Date of Accident - February 9, 2009. Injured was walking down a concrete ramp with both hands on the handrails. Injured slipped on some loose pellets but caught and kept himself from falling. In so doing he received a strain/sprain to the back. Days Lost - 10

Concentrator Operations, Date of Accident - March 4, 2009. Injured was descending the stairway from the balling floor to the grade floor when he lost his footing on the bottom step. The loss of footing resulted in a fall and a contusion to the knee and a strain/sprain to the lower back/ Days Lost - 17

Pellet Operations, Date of Accident - May 5, 2009. Injured and a helper were trying to position a full 55 gallon drum onto a cradle when injured felt a pop in his knee. This resulted in a sprain/strain to the knee. Days Lost - 2

Pellet Maintenance, Date of Accident - May 8, 2009. Injured was lifting a section of conveyor belt in preparation for rigging and lifting with a crane. As injured bent down he felt a pull in his groin. This resulted in a sprain/strain to the groin. Days Lost - 1

Pellet Maintenance, Date of Accident - June 28, 2009, A line #2 Cooler Dump Arm had broken on Afternoon Shift, and the Afternoon Shift maintenance crew had prepped the area for replacement by the Night Shift Maintenance Crew. Injured and his partners had finished cleaning the dump arm shaft and had hoisted the new dump arm into position and started it onto the shaft (maybe a 16th of an inch or so) and suspended the arm from a chain jack. In order to fully install the dump arm they set up a combination of a spacer pipe and a hydraulic ram between the concrete pillar and the dump arm shaft to push the arm fully onto the shaft. With the spacer pipe against the pillar and the ram against the dump arm, injured positioned himself near the hydraulic ram with his right arm hooked under the spacer pipe to operate the ram and watch the dump arm as it was jacked onto the shaft. While bumping the ram to push the dump arm on, the spacer pipe and the hydraulic ram kicked out of position and pushed against injured's chest, pushing him about 8 to 10 feet away. This caused the stated injuries. One witness believed that the dump arm may not have been perfectly aligned onto the shaft. This caused a build up in pressure against the dump arm, and when the dump arm popped onto the dump arm shaft (approximately 2-2.5 inches) the spacer pipe and the ram kicked out of position due to the sudden loss of pressure. This resulted in bruised ribs. Days Lost - 40

Pellet Maintenance, Date of Accident - August 14, 2009. Injured and his partner were pressure washing cooler carrier wheels in the steam room. The wheel involved in the incident was standing upright and had already been cleaned. Injured turned around to clean up the next wheel so he could attach the cooler wheel lifting device, so the next wheel could be stood up for final cleaning. The wheel that was standing upright began to roll towards injured. His partner attempted to warn him of the wheel's movement, but injured could not hear him over the noise of the steam cleaner and the Broderson crane. The wheel rolled off of the drain cover it was on and fell pinning injured's leg/ankle to the floor and the pallet that the next wheel to be cleaned was lying on. The weight of the fallen wheel required his partner to use the Broderson crane to pick the fallen wheel off of the injured party. Days Lost - 26

HIBBING TACONITE COMPANY

No Lost Time Injuries In 2009

KEEWATIN TACONITE

Utility Technician, Date of Accident - December 9, 2009 - Injured was in the process of mopping the floor when she felt a "pop" in her back. This resulted in a back strain. Days Lost - 22

Supervisor, Date of Accident - December 11. 2009. Injured was on the edge of newly constructed remote sump to lift a B.O. sump pump that had broken the previous lifting rope. The rigging was now nylon rope attached to a 20' section of hose that in turn was attached to the sump pump with cast aluminum fittings. The pump weighed approximately 80# and the discharge end of the hose was not attached to anything. Hoisting was done with a Caterpillar model 365B excavator. While lifting, with the injured directing, the fitting between the pump and the hose failed allowing the hose, with metal ends, to hit the injured in the head. He was standing near the edge of the sump, where the pump was going to be placed after the lift. This resulted in a head bruise, a 3-4" head laceration, sub-arachnoid bleeding, and torn muscles in the posterior region of the neck. Days Lost - 5

NORTHSHORE MINING COMPANY

Babbitt Mine

Mine Maintenance, Date of Accident - February 24, 2009. Injured was using a "Rivet Buster" type of jackhammer to clean and free up track rollers on the side frame of a P&H 120A drill. While using the jackhammer to remove the frozen dirt and ice, the air hose connection fitting broke and the pressurized hose and air fitting struck the employee on the right side of the face, just under the lip. This resulted in the employee receiving 2 stitches and 2 chipped teeth. Days Lost None

Silver Bay

Plant Maintenance Electrician, Date of Accident - March 28, 2009. Injured was exiting a pickup truck. When he stepped out of the cab he slipped on snow covered ice and fell on his left side, injuring his rib cage. Days Lost - 20

USS CORPORATION, MINNTAC MAINTENANCE

Ironworker, Date of Accident - January 9, 2009. Injured was grinding slag from the edges of floor liner plates. While moving the grinder, it contacted injured's leg. This resulted in a laceration to right leg, just above the knee. Days Lost - None

MTM, Date of Accident - August 22, 2009. Injured was assigned the task of removing bucket lip shrouds on the stated shovel. He had cleaned the area of the J-bolts that held the (two piece) shrouds to the bucket lip. He then proceeded to cut the J-bolts with a torch. He then placed a brass hammer on the back side of the shroud lip and began hitting the hammer with a steel hammer. After the shrouds were removed, he and a partner who had arrived to help, started installing the new shrouds. At about this time, injured felt a tingling sensation to his left knee and upon rolling up his pants, noticed a stream of blood coming from the side of his knee. This was later found to be the area where the two pieces of metal, fused together, entered the leg. One piece was brass from the hammer and the other was steel from the shroud. This resulted in a shrapnel wound to the left knee. Days Lost - 2

USS CORPORATION, MINNTAC MINE

Operations Technician, Date of Accident - January 13, 2009. Injured was descending the stairs on a production truck when he tripped on a cable. This resulted in a strain/sprain. Days Lost - None

Mobile Equipment Operator, Date of Accident - January 28, 2009. Injured was installing a length of steel pipe on a sump when the pipe shifted and pinched his left index finger between the pipe and a ladder rung. This resulted in a laceration to the finger. Days Lost - None

Shovel Operator, Date of Accident - June 26, 2009. Injured was spotting and dumping trucks on the #51 waste rock stockpile in the West Pit. He questioned in his mind the height of the berm he was leaving and decided to egress the loader for an on ground evaluation. A six foot berm height is required and the injured is six foot tall. As he was to climb down the last section of ladder, his foot slipped off the top step causing him to fall to the ground landing on his chest and both wrists resulting in the stated injuries. From the top step of the vertical ladder to the ground is 59 inches. This resulted in broken right and left wrists, a fracture of the left elbow and facial contusions. Days Lost - 40

Utility Person, Date of Accident - September 9, 2009. Injured was in the process of cleaning the tail end area of the 009-02 conveyor of rock and mud. She positioned herself on top of the pile to be able to hose and follow the material down to where the shovel guards are located. As she stepped off the pile to the floor level, she tripped on the tangled hose which laid in front of her. This resulted in a vertical fracture of the left knee cap. Days lost - None

Utility Technician, Date of Accident - October 17, 2009. Injured was walking down a utility tunnel when his knee gave out, causing him to fall. This resulted in a sore shoulder. Days Lost - None

Hybrid, Date of Accident - October 29, 2009. Injured was installing a belt roller when his finger got pinched between the roller and the wash pan. This resulted in a laceration to the finger. Days Lost - None.

Mobile Equipment Operator, Date of Accident - November 23, 2009. While the Operator's truck was being loaded, a large chunk of material was dropped into the box. This caused a jarring in the cab, which resulted in a sore back. Days Lost - None

USS CORPORATION, MINNTAC PLANT

Utility Technician, Date of Accident - January 28, 2009. Injured was cleaning up some pellet spillage. In the process he slipped on some ice and pellets, which resulted in a fractured ankle. Days Lost - 70

MTM, Date of Accident - January 30, 2009. Injured was descending a flight of stairs when he slipped and fell forward. In trying to catch himself, he dislocated his shoulder. Days Lost - None

MTM, Date of Accident - February 2, 2009. Injured was removing a full bag of garbage from a garbage can. As he was lifting, his hand slipped off of the bag and struck the concrete wall. This resulted in a fractured hand. Days Lost - None

Hybrid, Date of Accident - February 6, 2009. Injured was attempting to remove slag that was stuck between a dump truck box and the tail gate. When the slag dislodged, the employee's finger was pinched between the box and the tail gate, causing a laceration. Days Lost - None

Painter, Date of Accident - June 10, 2009. After mixing some epoxy paint, the employee complained of difficulty breathing. The employee returned to work with restricted duty. Days Lost - None

Utility Technician, Date of Accident - June 30, 2009. Injured was helping his partner remove a bolt when his partner's wrench slipped off of the bolt. The wrench struck injured in the upper lip causing a laceration. Days Lost - None

Utility Technician, Date of Accident - December 4, 2009. While walking across wet concrete, injured slipped and hyper extended his knee. Days lost - 10

Hybrid, Date of Accident - December 30, 2009. Injured was pulling on a wrench to loosen a bolt. While pulling the wrench, injured felt pain radiating across his right buttock and down his leg. This resulted in a strained back. Days Lost - 10

MAGNETATION

Plant Operator, Date of Accident - May 20, 2009. Injured was stepping down off of the water truck when he slipped off the step. This resulted in a sprained left ankle. Days Lost - 22