


Repair Time Comparison

A sampling from dozens of examples collected from Minnesota dealerships representing various brands.

	1	2	3	4
Repair	Customer Pay	Warranty	Recall	Difference
 Timing Chain Replacement	7.3 Hours ALLDATA	5.4 Hours	3.7 Hours	↓ 49%
 Cylinder Head Replacement	21.5 Hours	10.5 Hours	N/A	↓ 51%
 Front Coil Springs Replacement	4.6 Hours ALLDATA	1.1 Hours	N/A	↓ 76%
 Fuel Pump Replacement	2.1 Hours ALLDATA	1.1 Hours	N/A	↓ 48%
 Piston Replacement	41.5 Hours MOTOR	30.9 Hours	N/A	↓ 25%
 Steering Shaft Repair	2.1 Hours ALLDATA	0.8 Hours	N/A	↓ 62%