

ENFORCER™ CAMERA CALIBRATION REPORT



Camera Settings

Location:	500 Block Marie
Serial number:	70:B3:D5:B7:DD:34
Firmware version:	1.1.42.11
Mounting height:	6.6 ft
Distance from the edge of the road:	7.5 ft
Installation side:	Right

Calibration

Performed by:	Administrator
Started:	2025-09-12 13:40:55
Finished:	2025-09-12 13:49:14
Number of samples:	7 (For valid calibration you need at least 60% of valid samples)
Number of valid samples:	5 (71%)
Status:	Passed

Samples

<i>Date/Time</i>	<i>From (ft)</i>	<i>To (ft)</i>	<i>Valid?</i>
2025-09-12 13:42:53	37.07	110.96	Yes
2025-09-12 13:43:21	31.82	98.36	Yes
2025-09-12 13:44:45	35.47	91.08	Yes
2025-09-12 13:45:04	38.52	77.26	No
2025-09-12 13:45:08	31.53	80.05	No
2025-09-12 13:47:00	36.32	87.99	Yes
2025-09-12 13:47:17	31.3	104.89	Yes